

# Device Errata

## mPCIe Adapter Board

NimbeLink // Products

Published // February 18, 2016



© NimbeLink Corp. 2017. All rights reserved.

NimbeLink Corp. provides this documentation in support of its products for the internal use of its current and prospective customers. The publication of this document does not create any other right or license in any party to use any content contained in or referred to in this document and any modification or redistribution of this document is not permitted.

While efforts are made to ensure accuracy, typographical and other errors may exist in this document. NimbeLink reserves the right to modify or discontinue its products and to modify this and any other product documentation at any time.

All NimbeLink products are sold subject to its published Terms and Conditions, subject to any separate terms agreed with its customers. No warranty of any type is extended by publication of this documentation, including, but not limited to, implied warranties of merchantability, fitness for a particular purpose and non-infringement.

NimbeLink is a registered trademark, and Skywire is a registered trademark, of NimbeLink Corp. All trademarks, service marks and similar designations referenced in this document are the property of their respective owners.

# Table of Contents

Table of Contents	2
<b>NimbeLink Part numbers Affected</b>	<b>3</b>
<b>Applications Affected</b>	<b>3</b>
<b>How to Identify Affected Product</b>	<b>3</b>
<b>Workarounds</b>	<b>4</b>
<b>Board Rework</b>	<b>4</b>
<b>Contact</b>	<b>4</b>

# 1 NimbeLink Part numbers Affected

Affected Part Numbers
NL-AB-MPCIE

## 2 Applications Affected

This Errata affects applications using the mPCIe adapter board. Some Skywire® modem combinations are not detected by host processor operating systems because the USB interface is not instantiated.

This Errata affects all 20027 Rev A mPCIe Adapter boards that do not have a white manufacturer's sticker on the back and boards with a manufacturer's sticker with a date code before 0116.

This Errata does not affect your design if any of the following is true:

- 1) mPCIe PCB is revision B or greater
- 2) mPCI manufacture serial code (located on the back of the board) is newer than 0116:

## 3 How to Identify Affected Product

The manufacturer date code is located on the back side of the mPCIe Adapter Board on a white sticker. The manufacturer revision number is at the end of the first



line of printed text on the sticker and is of the form of 'WWYY' where WW is the manufacturing week and YY is the manufacturing year. This Errata affects all mPCIe boards with a date code before 0116.

## 4 Workarounds

For customers that have the affected product, you have two options:

- 1) Modify existing mPCIe Adapter Board hardware to replace resistor R5 (see section 5).
- 2) Request an RMA for the affected product via [Product.Support@NimbeLink.com](mailto:Product.Support@NimbeLink.com)

## 5 Board Rework

The Errata can be repaired on affected product by replacing resistor R5 with a size 0603 zero (0) ohm resistor. Replacing R5 will not invalidate the product warranty, however, poor workmanship can damage the board and invalidate the warranty.

## 6 Contact

For further information please contact NimbeLink Technical Support at [Product.Support@NimbeLink.com](mailto:Product.Support@NimbeLink.com).

# Revision History

REV	EDITOR	DESCRIPTION	APPROVAL	DATE
A	GJN	Initial draft		2016/02/17