

## Errata

The following are known problems with Rev. A of the AT89S2051/S4051 device:

### 1. JBC to TF0, TF1, IE0, IE1

JBC may cause a loss of interrupt information if used with any interrupt flag (see item #2 for SCON). Therefore JBC should not be used to poll for interrupt flags.

#### Problem Fix/Workaround:

```
POLL: JBC FLAG, NEXT
      SJMP POLL
```

#### should be replaced by:

```
POLL: JNB FLAG, POLL
      CLR FLAG
      SJMP NEXT
```

### 2. Read-Modify-Write to SCON (SETB, CLR, CPL, ANL, ORL, XRL, JBC)

Read-Modify-Write (RMW) instructions may cause a loss of UART interrupt information if used with any bit in SCON, i.e. the RMW instructions need to be treated as a direct move to SCON such as MOV SCON,#IMM. These instructions may be used when it is not possible for the interrupt to occur at the same time as the instruction is being executed, which means in the following circumstances::

- A. The UART is not currently operating, **or**
- B. Within a short period of time after TI or RI is set during half-duplex communications, **or**
- C. Within a short period of time after both TI and RI are set during full-duplex communications, and before the next byte is transmitted.

### 3. Read-Modify-Write to ACSR (ANL, ORL, XRL)

Read-Modify-Write instructions may cause a loss of Comparator interrupt information if used with any bit in ACSR, i.e. the RMW instructions need to be treated as a direct move to ACSR such as MOV ACSR,#IMM. These instructions may be used when it is not possible for the interrupt to occur at the same time as the instruction is being executed, which means in the following circumstances:

- A. The Comparator is not active, **or**
- B. Within a short period of time after CF is set, **or**
- C. The flag is level-sensitive and the input condition will last through the next instruction, **or**
- D. Any time, if the application can afford to miss an edge event. The actual miss frequency will depend on the application code.

### 4. Interrupt Recovery from Power-down Mode

When attempting interrupt recovery from power-down, the external interrupt pins  $\overline{\text{INT0}}$  (P3.2) and  $\overline{\text{INT1}}$  (P3.3) should not transition low until at least 10  $\mu\text{s}$  after entry into power-down. If the pins are low immediately before entering power-down, or go low while attempting to enter power-down, the device can get stuck in a power-down-like state requiring a power cycling sequence to wake up.



## AT89 Microcontrollers

## AT89S2051 AT89S4051 Rev. A Errata Sheet





## Atmel Corporation

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 487-2600

## Regional Headquarters

### Europe

Atmel Sarl  
Route des Arsenalux 41  
Case Postale 80  
CH-1705 Fribourg  
Switzerland  
Tel: (41) 26-426-5555  
Fax: (41) 26-426-5500

### Asia

Room 1219  
Chinachem Golden Plaza  
77 Mody Road Tsimshatsui  
East Kowloon  
Hong Kong  
Tel: (852) 2721-9778  
Fax: (852) 2722-1369

### Japan

9F, Tonetsu Shinkawa Bldg.  
1-24-8 Shinkawa  
Chuo-ku, Tokyo 104-0033  
Japan  
Tel: (81) 3-3523-3551  
Fax: (81) 3-3523-7581

## Atmel Operations

### Memory

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 436-4314

### Microcontrollers

2325 Orchard Parkway  
San Jose, CA 95131, USA  
Tel: 1(408) 441-0311  
Fax: 1(408) 436-4314

La Chantrerie  
BP 70602  
44306 Nantes Cedex 3, France  
Tel: (33) 2-40-18-18-18  
Fax: (33) 2-40-18-19-60

### ASIC/ASSP/Smart Cards

Zone Industrielle  
13106 Rousset Cedex, France  
Tel: (33) 4-42-53-60-00  
Fax: (33) 4-42-53-60-01

1150 East Cheyenne Mtn. Blvd.  
Colorado Springs, CO 80906, USA  
Tel: 1(719) 576-3300  
Fax: 1(719) 540-1759

Scottish Enterprise Technology Park  
Maxwell Building  
East Kilbride G75 0QR, Scotland  
Tel: (44) 1355-803-000  
Fax: (44) 1355-242-743

### RF/Automotive

Theresienstrasse 2  
Postfach 3535  
74025 Heilbronn, Germany  
Tel: (49) 71-31-67-0  
Fax: (49) 71-31-67-2340

1150 East Cheyenne Mtn. Blvd.  
Colorado Springs, CO 80906, USA  
Tel: 1(719) 576-3300  
Fax: 1(719) 540-1759

### Biometrics/Imaging/Hi-Rel MPU/ High Speed Converters/RF Datacom

Avenue de Rochepleine  
BP 123  
38521 Saint-Egreve Cedex, France  
Tel: (33) 4-76-58-30-00  
Fax: (33) 4-76-58-34-80

---

## Literature Requests

[www.atmel.com/literature](http://www.atmel.com/literature)

**Disclaimer:** The information in this document is provided in connection with Atmel products. No license, express or implied, by estoppel or otherwise, to any intellectual property right is granted by this document or in connection with the sale of Atmel products. **EXCEPT AS SET FORTH IN ATMEL'S TERMS AND CONDITIONS OF SALE LOCATED ON ATMEL'S WEB SITE, ATMEL ASSUMES NO LIABILITY WHATSOEVER AND DISCLAIMS ANY EXPRESS, IMPLIED OR STATUTORY WARRANTY RELATING TO ITS PRODUCTS INCLUDING, BUT NOT LIMITED TO, THE IMPLIED WARRANTY OF MERCHANTABILITY, FITNESS FOR A PARTICULAR PURPOSE, OR NON-INFRINGEMENT. IN NO EVENT SHALL ATMEL BE LIABLE FOR ANY DIRECT, INDIRECT, CONSEQUENTIAL, PUNITIVE, SPECIAL OR INCIDENTAL DAMAGES (INCLUDING, WITHOUT LIMITATION, DAMAGES FOR LOSS OF PROFITS, BUSINESS INTERRUPTION, OR LOSS OF INFORMATION) ARISING OUT OF THE USE OR INABILITY TO USE THIS DOCUMENT, EVEN IF ATMEL HAS BEEN ADVISED OF THE POSSIBILITY OF SUCH DAMAGES.** Atmel makes no representations or warranties with respect to the accuracy or completeness of the contents of this document and reserves the right to make changes to specifications and product descriptions at any time without notice. Atmel does not make any commitment to update the information contained herein. Atmel's products are not intended, authorized, or warranted for use as components in applications intended to support or sustain life.

© Atmel Corporation 2005. All rights reserved. Atmel®, logo and combinations thereof, Everywhere You Are® and others, are registered trademarks or trademarks of Atmel Corporation or its subsidiaries. Other terms and product names may be trademarks of others.



Printed on recycled paper.

3569A-MICRO-6/05