

Customer Information Notification

2020050061

13-Aua-2020 Issue Date: Effective Date: 14-Aug-2020

Here's your personalized quality information concerning products Digi-Key purchased from NXP. For detailed information we invite you to view this notification online

This notice is NXP Company Proprietary.



QUALITY

Management Summary

There is a issue in SW L4.19 release. We should notice customers to use correct version and avoid issue.

Change Calegory	
[] Wafer Fab Process	

[] Wafer Fab Materials

[] Wafer Fab Location

[] Assembly[] Product Marking [] Test Process Location [] Assembly[] Mechanical []Test Materials Specification Process []Assembly[] [] Test Packing/Shipping/Labeling Equipment spec./Test Location

[] Design

[] Errata

[] Electrical coverage

[] Firmware

[X] Other - Software

Wrong Voltage Setting and Risk Burning 845/815 on 4.19.xx and 5.4.xx Linux and Android Pre-build Demo Image

Description

LDO1/2 voltage of rohm,bd71847 are set wrong on L4.19 after kernel bootup : LDO1@3.0V --NVCC_SNVS_1V8 LDO2@0.9V ----VDD_SNVS_0V8 With the below kernel print log: [0.931167] Ido1: Bringing 1800000uV into 3000000-3000000uV 0.938256] Ido2: Bringing 800000uV into 900000-900000uV The issue is impacting 8MMINILPD4-EVK, MX8MMINID4-EVK and MX8MNANOD4-EVK boards. The wrong voltage is vialating the spec and might damage IOs.

The related SW release were set invalid in website after May. 28th Suggesting customer use latest SW release or apply proper patches for these boards. Since there are different bd71847 drivers/dts used on L4.14/L4.19/L5.4, there are different patches for this issue, please appy the correct patch on the right release branch: 1). imx 4.14.98 2.3.0: 0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch 0003-MLK-23275-3-regulator-bd71837-correct-ldo1-ldo2-grou.patch 2). imx_4.19.35_1.1.0: 0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-.patch

0003-MLK-23846-ARM64-dts-freescale-fsl-imx8mn-ddr4-evk-co.patch 3). imx_5.4.3_2.0.0: 0001-MLK-23275-1-ARM64-dts-freescale-fsl-imx8mm-evk-corre.patch 0002-MLK-23275-2-ARM64-dts-freescale-imx8mn-ddr4-evk-corr.patch

0003-MLK-23844-1-ARM64-dts-freescale-imx8mn-ddr4-evk-clea.patch

0004-MLK-23844-2-ARM64-dts-freescale-imx8mm-correct-VDDAR.patch

Reason

Notice customers not using wrong SW version or download the correct SW version.

Identification of Affected Products

it is SW error, and No impact to Soc.

Anticipated Impact on Form, Fit, Function, Reliability or Quality

No impact on form, fit, function, reliability or quality.

Data Sheet Revision

No impact to existing datasheet

Contact and Support

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards.

Customer Focus, Passion to Win.

NXP Quality Management Team.

About NXP Semiconductors

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization.

This message has been automatically distributed. Please do not reply.

|--|

NXP Semiconductors

© 2006-2010 NXP Semiconductors. All rights reserved.

Affected Part Numbers

8MMINILPD4-EVK 8MNANOD4-EVK 8MMINID4-EVK