

Notice #220916-03

Product Change Notification		Date 16/09/2022	
Product	Digi ConnectCore 6 Plus		
Reason for Change			
Technical Requiremen	nt Product Transition		
Customer Requireme		Product Discontinuation	
Quality Improvement		Product Enhancement	
Quanty improvement		Other (Brand Change)	
	Ctrict (Brand Change)		
Description of change	Digi received reports from customers about a sporadic issue / system instability, resulting in a kernel crash, in a small number of SOM devices. After technical investigation and testing it was determined that the following update solved the issue. A change in the DDR3 memory configuration / increase of the drive strength (DSE) from 40 Ohm to 34 Ohm fixes the instability problem. The u-boot software was updated to incorporate the change and released to github. Additional reports about a sporadic system freeze during the Linux boot-up		
	sequence has been investigated. The issue occurs who initializes the VPU and the voltage rail of this hardwar reached the minimal voltage required. The problem was fixed by initializing the LDO_PU regulated boot loader, so the voltage has reached the requived is initialized. The modifications have been validated by Digi and the the issues.	re module has not ulator already in the u- uired level before the	
Affected Part Numbers	ConnectCore 6 Plus ConnectCore 6 Plus System-on-Module (SOM) CC-WMX-KK8D-TN CC-MX-LL7C-ML ConnectCore 6 Plus professional development kit CC-WMX6P-KIT		
Timing of Change	Software patches are available on Github for all differ		
	branches now: https://github.com/digi-embedded/m	eta-digi <u>/</u>	
Notes	Digi recommends applying the change for new produ issues have been seen with products in the field.	cts and if stability	
Authorization	Digi International OEM Solutions Product Managemen	nt	