

Global Change Notification (GCN)

Product Family	Terminal Strain Relief	10638693	
		GCN Number	
Series	90198	May 26, 2014	
		Date Issued	
Reason For Change	MOQ (Not SPQ)		
Change Description	This is to inform you that Molex is changing the Minimum Order Quantity (MOQ)for the part No 90198-0001 from 30K to 50K pieces. The reason for this change is there are 10k terminals on a reel and five reels fit in a box. Currently when we are shipping orders we have to break down finished boxes, take out two reels and replace with empty reels. This result in extra handling of the product and the generation of partial box and a risk to product getting damage. The other part in this product family 90198-0002 already has a 50k MOQ		
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-r	mail message.	
Reason For Short Notice Exception			
Assessment Of Change (How Product Will Be Qualified & Validated)			
Internal Molex Qualification Date (Planned Date Information Available)			
Sample Availability Date (Changed Part)			
Date of Implementation	November 26, 2014		
Method of Identifying Change	Quanity in box will change		
Recommended Replacement Parts			
Last Time Buy Date for Obsolete Parts			
Last Time Ship Date for Obsolete Parts			

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com