

Product Change Notification (PCN)

PCN Number			511209	Date Issued	December 17, 2021		
Reason for Change			Equipment Transfer, Production Transfer or Rearrangement				
Change Type Description			This letter is to inform you that production of the part(s) identified in this notice is being moved to a different production location. No changes will be made to the product as a result of this move.				
	Reason for Sh	ort Notice	Special Request				
	Assessment of Change			Passed FAI			
Internal I	Internal Molex Qualification Date			March 12, 2022			
	Sample Availability Date (Changed Part)			March 12, 2022			
Plann	Planned Implementation Date			April 15, 2022			
Meth Before Change	Method of Identifying Change Before Change			Change			
Production plant lo			Change o				
	Current	After change	productio	in of the 0.35 BB SSB10RP PLUG lines	r global manufacturing footprint, Molex will relocate from Japan to Molex Vietnam production facility.		
Manufacturing location	Molex Kagoshima	Molex Vietnam		sfer will started in Q1 2022 and target to illt as need to ensure a seamless transfe	complete in 2022. Buffer stock and capacity tooling er.		
Product	Current	No change	Product in				
Machine/Tooling	Current	No change		t to form, fit and function. ge in product specification.	A STATE OF THE STA		
Man	Current	Change		ber impacted :	W		
Control plan	Current	No change		-XXXX (0.35 BB H=1.0 SSB10RP PLUG AS	SSY)		
			● Identificat For 1st lot Molex wil numbero	ion report and samples : Available as ex- tion : t of production starting by Vietnam plant II add "P" at the end of Traceability on the label as signal to recognize produ e by Vietnam.	Trona Constantia		

molex[®]

Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:511209**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com

Affected Parts:

505417-1410
505417-3010