



CUSTOMER OPERATIONS
 160 RIO ROBLES
 SAN JOSE, CA 95134

PDN #: M000861

DATE: 19-Sep-2017

PRODUCT DISCONTINUANCE NOTICE

Notice Type	Maxim Part Number	Recommended Replacement	Last Order Date	Last Delivery Date	Reason
Reactivation	MAX17019ATM+	N/A			Part reactivated from prior notice: M000858
Reactivation	MAX17019ATM+T	N/A			Part reactivated from prior notice: M000858
Discontinuance	MAX14798EWP+	MAX14940GWE+	19-Sep-2018	21-Mar-2019	The part was not released
Discontinuance	MAX34451ETNA1+	MAX34451ETNA2+	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX34451ETNA1+T	MAX34451ETNA2+T	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	MAX9286EGTN+	MAX9286GTN/V+	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	VT1312MFQ	N/A	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	VT1315SFCR	N/A	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	VT1315SFCX	N/A	19-Sep-2018	21-Mar-2019	Part can no longer be manufactured
Discontinuance	VT234AWFQR-ADJ	VT234AWFQX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT234WFQR-ADJ	VT234WFQX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT237WFQR-ADJ	VT237WFQX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT239WFQR-ADJ	VT239WFQX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT239WFQR-ADJ-004	VT239WFQX-ADJ-004	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT250AFCR-ADJ	VT250AFCX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT358FCR-ADJ	VT358FCX-ADJ	19-Sep-2017	19-Sep-2017	Part can no longer be manufactured
Discontinuance	VT505AFQ	VT505BFQ	19-Sep-2017	19-Sep-2017	The part was not released

LAST DAY FOR DISTRIBUTORS TO RETURN PRODUCT: 20-Oct-2017