Dialight			
Customer	Product/Process Cha	nge Notification	
		PCN # 99899	
		Issued Date: 15-Dec-22	
		Issued By:	
		Author: John Vines	
Change affects whole product family?	No		
Part #'s affected (See attached if entire product			
137-7336-09-203 Front Mount sub-miniature pane	i indicator		
Description of Change:			
Product Obsolescence			
Floudet Obsolescence			
Reason for Change:			
Because component for product not purchased	since 2014. Vendor no longer	manufactures the bushing.	
volume too low to justify search for and tooling	_	C,	
Properties of Old vs. Changed Product:			
See mechanical comparison sheet			
Disposition of Old Product:			
OK to use			
	ediate		
Customer Feedback Expected by: N/A			
Additional Commenter (Include Detential Disks	if Americanista)		
Additional Comments: (Include Potential Risks			
Closest potential replacement is Dialight P/N 137-7 See mechanical comparison	236-09-201 Front/Rear Mount		
see mechanical comparison			
Supporting Qualification Data:			
L			