<b>PCN Number:</b> 20180516000		PCN Date:			May 21, 2018					
Title: Datasheet for LMK03806										
<b>Customer Contact:</b>	PCN Manage	er			Dep			Quality Services		
Change Type:						<u>-</u>		•		
Assembly Site			Design			Wa	fer	Bump Site		
		$\boxtimes$	Data Sheet			Wa	Wafer Bump Material			
Assembly Materials			Part number change			_	Wafer Bump Process			
Mechanical Specification		Щ	Test Site				Wafer Fab Site			
Packing/Shipping/Labeling		Ш	Test Process				Wafer Fab Materials			
B1 - 1161 -			Lifi esti es	Detaile	Wafer Fab Process					
Notification Details  Pagarintian of Change:										
Description of Change:  Texas Instruments Incorporated is announcing an information only notification.										
The product datasheet(s) is being updated as summarized below.										
The following change history provides further details.										
TEXAS										
INSTRUMENTS LMK03806										
SNAS522J – SEPTEMBER 2011 – REVISED MARCH 2018										
Changes from Revision I (November 2015) to Revision J Page										
Removed unresolvable cross-references.										
Added initial programming requirement of R3.										
Changed readback text from "rising" to "falling".										
Bolded pin 30 of register R3 for emphasis. 23										
Added table note to Default Device Register Settings After Power On Reset to clarify proper use of CLKout6										
Added note to Register R0 TO R5 regarding programming R3.										
The datasheet number will be changing.										
Device Family			Change From:			Change To:				
LMK03806			SNAS	SNAS522I S				SNAS522J		
These changes may be reviewed at the datasheet links provided.										
http://www.ti.com/product/LMK03806										
Reason for Change:										
To accurately reflect device characteristics.										
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):										
No anticipated impact. This is a specification change announcement only. There are no changes										
to the actual device.										
Changes to product identification resulting from this PCN:										
None.										
Product Affected:										
LMK03806BISO/NOP	LMK03806BISQE/NOPB LMK03806BISQX/NOPB									

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com