



Product Discontinuance Notice - PDN 19_0100 Rev. -

Analog Devices, Inc. Three Technology Way Norwood, Massachusetts 02062-9106

This notice is to inform you of a product discontinuance for certain ADI products (see Discontinued Parts Material List below). Any issues with this PDN must be sent to ADI as soon as possible. The information contained within this PDN is considered proprietary and should not be shared outside of your company. ADI contact information is listed below.

PDN Title:

DC988A-D Obsolescence

Publication Date: 17-Jan-2020

Last Time Buy Date: 06-Jan-2020

Last Time Ship Date: 10-Jan-2020

Revision Description:

Initial Release

Reason For Discontinuance

Cannot rebuild this board due to obsolete transformer TDK, LDT565630T-041. There is no transformers from TDK or another vendor with a similar footprint. The LT3585 is in very low, practically not existing, demand. So most practical solution is to obsolete DC988A-D, vs laying out new board and changing DS. We still have plenty of DC988A-A, thus customers who want to learn LT3585 functionality can use DC988A-A.

Comments

Cannot rebuild this board due to obsolete transformer TDK.

Supporting Documents None

For questions on this PDN, send email to the regional contacts below or contact your local ADI sales representative

Americas: PDN_Americas@analog.com	Europe: PDN_Europe@analog.com	Japan: PDN_Japan@analog.com
		Rest of Asia: PDN_ROA@analog.com

PDN 19_0100 Discontinued Parts Material List

Model	Product Family	Replacement Part	Pin To Pin Compatible	Comments
DC988A-D	LT3585	DC988A-A	no	

Appendix A - PDN 19_0100 Revision History

Rev	Publish Date	Rev Description
Rev. -	17-Jan-2020	Initial Release

Analog Devices, Inc. Proprietary Information

DocId:1454 Layout Rev:3 Parent DocId:None