

MICRON_FW change for M500IT

PCN: 34121

Published: 2021-03-15

| Туре: | Firmware Revision | | | |
|-----------------------------|--|--|----------------------|----------|
| Description: | Fix for drive busy error beginning at 28224 power on hours | | | |
| Reason: | Improved Product Quality and Reliability | | | |
| Product Affected: | M500IT | | | |
| Affected Micron Part Number | | Recommended Replacement | Customer Part Number | |
| Component | | | | |
| MTFDDAK128MBD-1AK12IT | YY | | | |
| MTFDDAK256MBD-1AK12ITYY | | | MTFDDAK256MBD-1AK1 | 2ITYY-ND |
| MTFDDAT064SBD-1AK12ITY | Y | | | |
| MTFDDAT128MBD-1AK12ITY | ΥY | | | |
| MTFDDAT128SBD-1AK12ITY | Y | | | |
| MTFDDAT256MBD-1AK12IT | ГҮҮ | | 557-1813-ND | |
| | | *Materials that have been ordered are in | bold. | |
| Method of Identification: | FW printed on label will show MU03 | | | |
| Micron Sites Affected: | MSB - Singapore | | | |
| Product Ship Date: | 2021-03-15 | | | |

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

 ${\bf Micron\ Confidential\ and\ Proprietary\ Information}$

Attachments

There are no attachments on this PCN