



Product Change Notification		Date April 16, 2021
Product	Digi TransPort WR11XT/WR21/WR31/WR44R/WR44RR	

Description of change	New firmware version 8.3.1.2 available for all WR11XT/WR21/WR31/WR44R/WR44RR products. This is a mandatory release for all North American products. Digi recommends all customers update their WR products to firmware v8.3.1.2
------------------------------	---

Reason for Change	New Firmware Version 8.3.1.2 provides: <ul style="list-style-type: none">• Enhancements• Bug Fixes• Security Fixes See Release Notes for more details.
--------------------------	--

Product Notice	<p>A new stable firmware version has been released for the WR11/WR21/WR31 products, version 8.3.1.2. Use the link below to view the full list of changes, features, and fixes included in the new firmware.</p> <p>WR-series Release Notes</p> <p><u>To take advantage of the new features, you must take action to update your device.</u> Refer to the instructions to update your firmware in the release notes above for more information.</p> <p>Any questions or concerns about the new firmware, or for assistance updating your device(s), please contact the Digi Support team at tech.support@digi.com.</p>
-----------------------	---

Affected Part Numbers	WR11-L700-DE1-XB, WR11-M300-DE1-XB, WR11-M400-DE1-XB, WR11-M600-DE1-XB, WR11-M900-DE1-XB
------------------------------	--

	<p>WR21-M22B-DE1-SB, WR21-M52A-DE1-TB, WR21-M52B-DE1-SB, WR21-M72B-DE1-SB, WR21-D52A-DE1-TA, WR21-R52A-DE1-TB, WR21-R32A-DE1-TB</p> <p>WR31-M82A-DE1-TB, WR31-L92A-DE1-TB, WR31-M52A-DE1-TB, WR31-M72A-DE1-TB, WR31-M22A-DE1-TB, WR31-D52A-DE1-TB</p> <p>WR44-00G4-CE1-MC, WR44-L5A3-CE1-RF, WR44-L5F1-TE1-RF, WR44-L5G1-TE1-RF, WR44-L900-AE1-RF, WR44-L9F1-AE1-RF, WR44-L9G4-AE1-MC, WR44-L9G4-AE1-MD, WR44-M2F1-NE1-RF, WR44-M800-AE1-RF, WR44-M8G4-AE1-MD, WR44-L500-TE1-RF, WR44-L900-CE1-RF, WR44-M700-CE1-RF, WR44-M8F1-AE1-RF</p>
--	---

Timing of Change	Effective Immediately
-------------------------	-----------------------