

# **Customer Information Notification**

2021040331 : PCF8551 Datasheet 9 Clock Pulses after Power-On Requirement

Note: This notice is NXP Company Proprietary.

#### Issue Date: Apr 23, 2021 Effective date: Apr 30, 2021

Here is your personalized notification about a NXP general announcement.

For detailed information we invite you to view this notification online

#### Management summary

Updated sections 7.3 "Starting and Resetting the PCF8551", 7.3.2 "Power-On Reset (POR)" and 15.1 "Power-on Reset" of the Datasheet, to ensure

the users send nine clock pulses immediately after power-on (see also UM10204) for the proper device operation; if the POR does not work properly.

### **Change Category**

[ ]Wafer Fab Process	[]Assembly Process	[]Product Marking	[]Test Process	[]Design
[ ]Wafer Fab Materials	[]Assembly Materials	[]Mechanical Specification	[ ]Test Equipment	[X]Errata
[]Wafer Fab Location	[]Assembly Location	[]Packing/Shipping/Labeling	[]Test Location	[ ]Electrical spec./Test coverage

[]Firmware []Other

# PCN Overview Description

7.3 Starting and Resetting the PCF8551 Added "See also application information" comment.

7.3.2 Power-On Reset (POR) Added "The bus interface is initialized" comment.

15.1 Power-on Reset

The built-in POR block acts on the rising edge of the VDD supply voltage. Depending on the VDD rising edge in the application, the POR may not

work properly. Therefore to ensure proper device operation it is required to send nine clock pulses immediately after power-on (see also UM10204).

### Reason

The intend of these updates is to ensure that the customers send nine clock pulses immediately after power-on (see also UM10204) for the proper device operation; if the POR does not work properly.

#### Identification of Affected Products

Product identification does not change

# Anticipated Impact on Form, Fit, Function, Reliability or Quality

Customer must send nine clock pulses immediately after power-on (see also UM10204) for the proper device operation; if the POR does not work properly. **Data Sheet Revision** 

A new datasheet will be issued

## **Disposition of Old Products**

Existing inventory will be shipped until depleted The Datasheet changes won't affect the PCF8551 product inventory.

# Remarks

The PCF8551 device functionality won't be affected by these changes. **Contact and Support** 

For all inquiries regarding the ePCN tool application or access issues, please contact NXP "Global Quality Support Team".

For all Quality Notification content inquiries, please contact your local NXP Sales Support team.

At NXP Semiconductors we are constantly striving to improve our product and processes to ensure they reach the highest possible Quality Standards. Customer Focus, Passion to Win.

NXP Quality Management Team.

#### **About NXP Semiconductors**

NXP Semiconductors N.V. (NASDAQ: NXPI) provides High Performance Mixed Signal and Standard Product solutions that leverage its leading RF, Analog, Power Management, Interface, Security and Digital Processing expertise. These innovations are used in a wide range of automotive, identification, wireless infrastructure, lighting, industrial, mobile, consumer and computing applications.

You have received this email because you are a designated contact or subscribed to NXP Quality Notifications. NXP shall not be held liable if this Notification is not correctly distributed within your organization. This message has been automatically distributed. Please do not reply.

**NXP** Semiconductors

High Tech Campus, 5656 AG Eindhoven, The Netherlands

© 2006- 2021 NXP Semiconductors. All rights reserved.

Affected OPN	12NC
PCF8551ATT/AJ	935304761118
PCF8551ATT/AY	935304761518
PCF8551BTT/AJ	935305822118
PCF8551BTT/AY	935305822518