

Product Change Notification Form

Summary of Change: End of life for DB-TSSOP-SKT.

Reason for Change: Parts no longer available.

Detailed Description of Change:

The SSOP 28 Pin open top burn-in socket is no longer available. Therefore the DB-TSSOP-SKT product is being discontinued effective this date.

Products Affected:

Effected Product	Recommended Replacement Product
DB-TSSOP-SKT	NONE

Forecasted Key Dates and Milestones:

04/09/2012 PCN Date, the date this document was released for distribution to customers and distributors.

Reference Documents and Attachments:

None

FDI Contacts:

Contact the Product Team at FDI directly via email at support@teamfdi.com or via phone at 256-883-1240 or fax at 256-883-1241.