

Product Advisory

Issue Date: 15-November-2021

Change Description:





Products marking change from Ink Mark to Laser Mark

Parts Affected:

- PEX8609-BA50BC G
- PEX8604-BA50BI G
- PEX8606-BA50BI G
- PEX8615-BA50BC G
- PEX8617-BA50BC G
- PEX8619-BA50BI G
- PEX8615-BA50BI G
- PEX8609-BA50BI G
- PEX8619-BA50BC G
- PEX8604-BA50BC G
- PEX8606-BA50BC G
- PEX8608-BA50BC G
- PEX8613-BA50BC G
- PEX8614-BA50BC G
- PEX8618-BA50BC G

Description and Extent of Change:

This notification is to advise BRCM customer that top marking will change from ink marking to laser making. Example of product marking change in below:

	Current (Ink Marking)	To be (Laser Marking)
Marking on Mold		
Marking on Heat Sink		



Reasons for Change:

Ink marking process will be EOL (end of life) by 26-Dec-2021.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same. No impact on fit, form, function, quality & reliability.

Effective Date of Change:

Product shipments using this change will begin after 27-Dec-2021. Timing of shipment of the changed part will vary by part number depending on inventory levels.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.