

TAIWAN SEMICONDUCTOR	
	Dontinuing Notification
1. PDN No.: 2. To:	All involved customer
3. Contact Team:	PM Danny Lin
	QRA Sunnie Lin
4. Issue date:	2018/9/11
5. Affected product/ product family: KBL401G T0G	6. Recommended replacement: KBL401G T0
KBL401G TOG KBL402G TOG	KBL401G TO KBL402G TO
KBL403G T0G	KBL402G T0
KBL404G T0G	KBL404G TO
KBL405G T0G	KBL405G TO
KBL406G T0G	KBL406G T0
KBL407G T0G	KBL407G TO
KBL601G T0G	KBL601G T0
KBL602G T0G	KBL602G T0
KBL603G T0G	KBL603G T0
KBL604G T0G	KBL604G T0
KBL605G T0G	KBL605G T0
KBL606G T0G	KBL606G T0
KBL607G T0G	KBL607G T0
KBU401G T0G	KBU401G T0
KBU402G T0G	KBU402G T0
KBU403G T0G	KBU403G TO
KBU404G T0G	KBU404G TO
KBU405G T0G	KBU405G TO
KBU406G T0G	KBU406G T0
KBU407G T0G	KBU407G T0 KBU601G T0
KBU601G T0G KBU602G T0G	KBU602G T0
KBU603G T0G	KBU603G T0
KBU604G T0G	KBU604G T0
KBU605G T0G	KBU605G T0
KBU606G T0G	KBU606G TO
KBU607G T0G	KBU607G TO
KBU801G T0G	KBU801G T0
KBU802G T0G	KBU802G T0
KBU803G T0G	KBU803G T0
KBU804G T0G	KBU804G T0
KBU805G T0G	KBU805G T0
KBU806G T0G	KBU806G T0
KBU807G T0G	KBU807G T0
KBU1001G T0G	KBU1001G T0
KBU1002G T0G	KBU1002G T0
KBU1003G T0G	KBU1003G T0
KBU1004G T0G	KBU1004G T0
KBU1005G T0G	KBU1005G T0

\*\*\*\*\*\*The copyright of document and business secret belong to TSC, and no copies should be made without any permission \*\*\*\*\*\*



## Product Discontinuing Notification

	Some and a source of the second se	
KBU1006G T0G	KBU1006G T0	
KBU1007G T0G	KBU1007G T0	
7. Reason for discontinuing:		
7. Reason for discontinuing.		
No order in 3 years & No UL certification		
,		
8. Last time buy/ order entry:	Immediately	
9. Last shipment date:	Immediately	
10. Please let us know if you have any question/ comment:		
	·	
N/A		
11. Customer feedback required		
latest:		
(should we receive no feedback,	Immediately	
the change will be deemed as		
accepted!)		
12. Approved by:	Lloyd Sebial Opolentisima	