



MICRON_9300 11300DY0 Firmware Maintenance Release

PCN: 34466

Published: 2021-11-19

Type: Firmware Revision

Description:

Firmware improvements applied in this release:

1. Corrected OPROM values displayed in BIOS Human Interface Infrastructure (HII) form
2. Improved PCIe link training to handle specific OEM system corner-cases
3. Improved handling of unexpected shutdown sequence where 12V power is removed before CSTS.SHST is acknowledged by drive

Reason: Improved Product Quality and Reliability

Product Affected: All 9300 product configurations

| Affected Micron Part Number | Recommended Replacement | Customer Part Number |
|-----------------------------|-------------------------|-----------------------------|
| <u>MODULE</u> | | |
| MTFDHAL12T8TDR-1AT1ZABYY | | MTFDHAL12T8TDR-1AT1ZABYY-ND |
| MTFDHAL15T3TDP-1AT1ZABYY | | MTFDHAL15T3TDP-1AT1ZABYY-ND |
| MTFDHAL3T2TDR-1AT1ZABYY | | MTFDHAL3T2TDR-1AT1ZABYY-ND |
| MTFDHAL3T8TDP-1AT1ZABYY | | MTFDHAL3T8TDP-1AT1ZABYY-ND |
| MTFDHAL6T4TDR-1AT1ZABYY | | MTFDHAL6T4TDR-1AT1ZABYY-ND |
| MTFDHAL7T6TDP-1AT1ZABYY | | MTFDHAL7T6TDP-1AT1ZABYY-ND |

*Materials that have been ordered are in **bold**.

Method of Identification: Product Label

Micron Sites Affected: MSB - Singapore

Product Ship Date: 2021-12-19

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments

There are no attachments on this PCN