

Product Change Notice

Issue Date: October 2, 2018

Change Type:

New factory site code

Parts Affected:

BCM5719-4P
BCM5719-4PBLK
BCM5720-2P
BCM5720-2PBLK
BCM957302A3021AC
BCM957302M3020CBK
BCM957302M3021CBK
BCM957302M3022AC
BCM957302M3023CBK
BCM957302M3024CBK
BCM957304A3040C
BCM957304A3041CC
BCM957304A3042CC
BCM957304M3040C
BCM957304M3041C
BCM957314A3143CC
BCM957412A4120AC
BCM957412M4122C
BCM957412M4123C
BCM957414A4140C
BCM957414A4142CC
BCM957414M4142C
BCM957414M4143C
BCM957416A4160C
BCM957416M4163C
BCM957452M4520C
BCM957454A4540C
BCM957454M4540C

Description and Extent of Change:

An additional manufacturing site at Foxconn Bac Ninh located in Vietnam will be brought online. The same manufacturing processes at the current Foxconn Chongqing site will apply. To ensure product quality is equivalent to the current manufactured products, a transition build will be scheduled, evaluated, and first article inspections completed prior to approval for shipment from the additional facility.

Reasons for Change:

Additional capacity for continuity of supply

Effect of Change on Fit, Form, Function, Quality, or Reliability:

The device specification will remain the same, which will ensure product electrical performance remains the same. Appropriate electrical characterization and reliability qualification will be performed on representative products to ensure normal parametric distribution, consistent electrical performance, and reliability.



Effective Date of Change:

Product shipments using this change will begin in or after October 2018. Timing of shipment of the changed part will vary by part number depending on qualification completion, customer demand, and inventory levels.

Qualification Data:

Electronic First Article reports (FAIs) will be available on request.

Software / Firmware Update:

None

Recommended Action to be Taken by Customer:

Customer acknowledgement of this PCN and provide a new factory site code (if applicable) for CCX NetXtreme products produced at Foxcong Ban Ninh by October 5th, 2018.

Please contact your Broadcom Inc. field sales engineer or Contact Center for any questions or support requirements. Please return any response as soon as possible, but not to exceed 30 days.