

Product Change Notice

Issue Date: 2-September-2022

Change Description:

Introduction of new alternate manufacturing site

Parts Affected:

ASCB-JTC2-0A208	ASMB-KTC2-0B406	QSCB-UTC2-ZA21F	Q1MB-TTF2-ZB20B
ASCB-JTC2-0A308	ASMB-KTF0-0A306	QSMB-UTF0-0D22B	QSCB-TTF8-0K1AB
ASCB-RTC2-0A207	Q1MB-KTF0-ZA306	QSMB-UTF2-0E22B	QSCB-TTF8-0M10B
ASCB-RTCC-0A207	ASCB-UTC2-0A30B	Q2MB-UTF0-ZD20B	QSMB-TTF0-ZA20B
ASCB-RTF2-0A207	ASMB-UTF0-0D20B	QSCB-UTF8-ZB20B	QSMB-TTF2-0B20B
QSCB-RTF2-ZA207	ASMB-UTF2-0E20B	ASMB-TTF0-0A20B	ASCB-NTC2-0A307
ASCB-RTF2-0A307	Q1MB-UTF0-ZD20B	ASMB-TTF2-0B20B	ASCB-HTC2-0A309
ASMB-KTC0-0A406	Q9MB-UTF2-ZE20B		

Description and Extent of Change:

The new alternate manufacturing site has undergone Broadcom's qualification process and is deemed suitable as alternate site.

Reasons for Change:

Assurance of supply.

Effect of Change on Fit, Form, Function, Quality, or Reliability:

No change in fit, form and function as per datasheet.

Effective Date of Change:

Broadcom may ship products manufactured from both sites after 90 days from the above issuance date.

Qualification Data:

Qualification data will be available upon request.

Please contact your Broadcom field sales engineer or Contact Center for any questions or support requirements. Please acknowledge the receipt of the notice within 30 days of delivery. Lack of acknowledgement within 30 days constitutes acceptance of the change per JEDEC J-STD-046.