

**EFFECTIVE:** September 1<sup>st</sup>, 2022

Date: August 3<sup>rd</sup>, 2022

Dear Fluke Distributor,

Due to a component shortage, we are announcing the obsolescence of the FLUKE-830/BT Laser Shaft Alignment tool, effective September 1<sup>st</sup>, or until limited existing inventory is depleted.

We are also announcing the expedited release of the replacement product, FLUKE-831 Laser Shaft Alignment tool. The new product will feature new touchscreen tablet interface, with improved user experience and alignment features. **The FLUKE-831 will be open for orders September 1**<sup>st</sup>.

Master load sheets for the FLUKE-831 will be published on September 5<sup>th</sup>, with sales and marketing assets following on September 19<sup>th</sup>.

Fluke will maintain service of FLUKE-830/BT, per standard 5 year post obsolescence terms.

This letter is your notification of our product change.

## PLEASE INFORM ALL RELEVANT PERSONNEL WITHIN YOUR ORGANIZATION.

Obsolete Items			Replacement Items		
Product model	ltem Number	Description	Replacement Model	ltem Number	Description
FLUKE-830/BT	5237143	FLUKE-830/BT,LASER ALIGNMENT TOOL W/BLUETOOTH INSTALLED	FLUKE-831	5346724	FLUKE-831,LASER SHAFT ALIGNMENT TOOL

Should you have any questions regarding these changes, please contact your account manager or Fluke Inside Sales Team.