

Rocker Switches Obsolescence Announcement

Summary

Due to sales volume that has been much lower than anticipated with the rockers, Honeywell Sensing and Control has decided to obsolete this product offering, effective April 30, 2011. There are no plans to replace this offering with another rocker line at this time. We apologize for any inconvenience.

Affected Listings and Applicable Replacements

Current Series	Possible Replacement
FRN	No replacement planned
FRL	No replacement planned
SRN	No replacement planned
SRL	No replacement planned
MR93	No replacement planned
MRS93	No replacement planned
SR-01	No replacement planned

Action

- Notify existing customers of the planned obsolescence.
- Ensure last time buy orders are placed through the appropriate order management channels by April 30, 2011.

Additional Materials

- Access the AD/Rep Portal for a letter that you can modify and send to the customer.

Contact Information

For additional information, please contact Siva Iyer at [\[siva.iyer@honeywell.com\]](mailto:siva.iyer@honeywell.com).

March/2011

Copyright © 20xx Honeywell International Inc. All rights reserved.