

Product Change Notice

Date: 5/11/2020

The change will be applied on the MIC-7700Q-00A1 and MIC-7700H-00A1. If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

1. Reason for the Change: Update BIOS for product enhancement.

2. Affected Products: MIC-7700Q-00A1 and MIC-7700H-00A1. C-PN without doing custom BIOS. **T part numbers will NOT be changed unless customer requests to do.**

3. Impact on Application:

Item	Impact
Impact on Mechanical Design	No
Impact on Software Compatibility	Possible. Please download the latest drivers from Advantech product page.
Impact on Environment Characteristics	No
Impact on System Certifications ^{Note}	No
Physical Outlook Change	No
Ordering P/N Change	No
Cut-in Implement	New work order.

Note: Advantech CE/FCC, UL/CB, CCC certifications on this product.

4. Description of the Change(s):

Affected Models	Current Component	New Component	Category	Outlook Difference	Reason
MIC-7700Q-00A1	1420041366 (V2.00)	1420049346 (V2.02)	Firmware	No	1. Update ME code and Microcode for Intel Security Advisory (INTEL-SA-00241). 2. Update RSDIS Bit for Intel SPI security issue (ID: PSIRT-TA-201708-001).
MIC-7700H-00A1	1420041367 (V2.00)	1420049345 (V2.02)	Firmware	No	3. Add CPU TDP configurable function. 4. Fix COM1 LED and garbage message issues. 5. Update for other product enhancement functions.

5. Implementation & Schedule of the Change(s):

Affected Models	ECOM Number	Estimated Effective Date	Cut-in Implement	Change Description
MIC-7700Q-00A1	ECOM-162151	May. 15 th , '20	New work order	Change BIOS from 1420041366 (V2.00)to 1420049346 (V2.02)
MIC-7700H-00A1	ECOM-162151	May. 15 th , '20	New work order	Change BIOS from 1420041366 (V2.00)to 1420049346 (V2.02)

***Note: Cut-in progress depends on factory production schedule, what listed in this table is ESTIMATED time-frame.**

Contact Windows

PM	Mike Huang / mike.huang@advantech.com / 500-6322
AE	Benson Chou / Benson.Chou@advantech.com / 500-6164
