



MICRON_i200 microSD Card - Firmware Maintenance Release

PCN: 34319

Published: 2021-08-18

Type: Firmware Revision

Description: New firmware release 38.23.36 is replacing current production firmware. The key changes are:

1. Feature & performance enhancements
2. System stability improvements
3. General error and protocol improvements

Refer to attached firmware release note for more details.

Cards will begin shipping Sep 17, 2021 with the new firmware.

Reason: Improved Product Quality and Reliability

Product Affected: Micron i200 microSDHC UHS-I Card

Affected Micron Part Number <u>CARD</u>	Recommended Replacement	Customer Part Number
MTSD032AHC6MS-1WT		MTSD032AHC6MS-1WT-ND
MTSD064AHC6MS-1WT		

*Materials that have been ordered are in **bold**.

Method of Identification: New part number suffix is -BK07, etched on the back of the microSD card

Micron Sites Affected: Subcontractor

Sample Available: 2021-08-02

Product Ship Date: 2021-09-17

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

Micron Confidential and Proprietary Information

Attachments
