

Issued date: 2019-11-19

Product Change Notification

Dear Customer, we want to inform you about the following changes.

If you have any questions regarding this issue, don't hesitate to contact your salesperson or our customer service team. We're happy to help you.

Type of change:

☑ Product □ Process □ Specification □ End-of-life □ Other

Affected item(s):

Senseair S8 LP (Low Power) Article numbers: 004-0-0053, 004-0-0063, 004-0-0073, 004-0-0077, 004-0-0080

Suggested replacement product(s): N/A

Reason for change:

Update firmware on Senseair S8 LP products to improve internal producibility.

Expected influence on performance:

Improved producibility in in Senseair production but no difference on form fit or function on finished products.

Qualification, Validation plan and Results:

Tested and verified by Senseair. This firmware change has been made on other versions of the S8 sensor and has been proven successful.

Identification of changed item: None

Implementation date for change: During Q4 2019 Last ordering date: N/A