



Product Change Notification (PCN)

PCN Number	505590	Date Issued	May 25, 2018
Reason for Change	Equipment Transfer, Production Transfer or Rearrangement		
Change Type Description	This letter is to inform you that production of the part(s) identified in this notice are being moved to a different production or shipping location. No changes will be made to the product as a result of this move.		
Reason for Short Notice	New Capacity		
Assessment of Change	Product will be fully qualified before it is shipped. Qualification reports are available upon request.		
Internal Molex Qualification Date	July 25, 2018		
Sample Availability Date (Changed Part)	July 25, 2018		
Planned Implementation Date	August 01, 2018		
Method of Identifying Change	Factory order number		

RELEASED

Before Change

Before	After
Production location is Molex Japan	Production location is Molex Shanghai

After Change

Overview

- This is to announce production location change of Crimp receptacle terminal. Current manufacturing location is Molex Japan Shizuoka plant. however Molex Japan plant does not have enough production capacity and floor space. therefore Molex Shanghai plant (China) receive these stamping dies. Currently, 2759PBG and 2759G are plated by Molex Japan Kagoshima east plant. Molex Shanghai plant (China) will produce them in order to receive these stamping dies.
- Product Impact
 - "no impact to fit, form or function"
- Part Number Impact
 - "see attached impacted parts list"
- Qualification Reports and samples available upon request after the date shown above



Product Change Notification (PCN)

You may address any technical inquiries regarding this PCN by sending E-mail to pcn_coordinator@molex.com or your Local Sales Engineer.

Note: While responding, please retain "**PCN Notification:505590**" in the e-mail Subject line for faster response.

RELEASED

Molex, LLC
2222 Wellington Court
Lisle, IL 60532
TEL: 630-969-4747
www.molex.com

Molex Part #

8500114

8700001

8700042

8700043

39000278

39000279

39000281

39000282

39000283

39000285

39000308

39000324

39000327

39000327

39000331

39000331

Part numbers affected:

08-70-0002
39-00-0318
39-00-0324
39-00-0327
39-00-0331