Product Change Notification - SYST-15RCZS054

Date:

26 Nov 2018

Product Category:

USB Bridge

Affected CPNs:

📄 📊

Notification subject:

Data Sheet - USB4640/USB4640i High-Speed Inter-Chip (HSIC) USB 2.0 Hub and Flash Media Contro

Notification text:

SYST-15RCZS054

Microchip has released a new DeviceDoc for the USB4640/USB4640i High-Speed Inter-Chip (HSIC) USB 2.0 Hub and Flash Media Contro of devices. If you are using one of these devices please read the document located at USB4640/USB4640i High-Speed Inter-Chip (HSIC) USB 2.0 Hub and Flash Media Contro.

Notification Status: Final

Description of Change:

1) Changed “ATA2” to “ata2” in Table 4-3

2) Removed subsection, “4.4.7 IN-CIRCUIT EEPROM PROGRAMMING “in Section 4.4 “Internal Flash

Media Controller Extended Configurations”

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 26 Nov 2018

NOTE: Please be advised that this is a change to the document only the product has not been changed.

Markings to Distinguish Revised from Unrevised Devices: N/A

Attachment(s):

USB4640/USB4640i High-Speed Inter-Chip (HSIC) USB 2.0 Hub and Flash Media Contro

Please contact your local Microchip sales office with questions or concerns regarding this notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our PCN home page select register then fill in the required fields. You will find instructions about registering for Microchips PCN email service in the PCN FAQ section.

If you wish to change your PCN profile, including opt out, please go to the PCN home page select login and sign into your myMicrochip account. Select a profile option from the left navigation bar and

make the applicable selections.

Affected Catalog Part Numbers (CPN)

USB4640-HZH-03
USB4640-HZH-03-TR
USB4640I-HZH-03
USB4640I-HZH-03-TR