![Microchip logo]

Product Change Notification - SYST-07UKVO686

Date:
08 Jun 2019
Product Category:
Ethernet Switches
Affected CPNs:

Notification subject:

Data Sheet - VSC7442-02, VSC7444-02, VSC7448-02 and VSC7449-02 Data Sheet
Notification text:
SYST-07UKVO686
Microchip has released a new DeviceDoc for the VSC7442-02, VSC7444-02, VSC7448-02 and VSC7449-02 Data Sheet of devices. If
you are using one of these read the document located at VSC7442-02, VSC7444-02, VSC7448-02 and VSC7449-02 Data Sheet.

Notification Status: Final

Description of Change:
1) The Design Considerations chapter was updated with an issue regarding VCAP ES0 actions and
SDLB . For more information, see Design Considerations
The Pin Strapping table has been updated.

Impacts to Data Sheet: None

Reason for Change: To Improve Manufacturability

Change Implementation Status: Complete

Date Document Changes Effective: 08 Jun 2019

NOTE: Please be advised that this is a change to the document only the product has not been
changed.

Markings to Distinguish Revised from Unrevised Devices: N/A
Attachment(s):
VSC7442-02, VSC7444-02, VSC7448-02 and VSC7449-02 Data Sheet

Please contact your local Microchip sales office with questions or concerns regarding this
notification.

Terms and Conditions:

If you wish to receive Microchip PCNs via email please register for our PCN email service at our
PCN home page select register then fill in the required fields. You will find instructions about
registering for Microchips PCN email service in the PCN FAQ section.
If you wish to change your PCN profile, including opt out, please go to the PCN home page select
login and sign into your myMicrochip account. Select a profile option from the left navigation bar and
make the applicable selections.

Affected Catalog Part Numbers (CPN)

VSC7442YIH-02
VSC7444YIH-02
VSC7448YIH-02
VSC7449YIH-02