PRODUCT DISCONTINUATION NOTICE

PDN NO.: IKL2012-001

IXYS Product Type:	***Type***	***Recommended replacement***
	SLMD121H04	SLMD121H04L
	SLMD121H06	SLMD121H06L
	SLMD121H08	SLMD121H08L
	SLMD121H09	SLMD121H09L
	SLMD121H10	SLMD121H10L
	SLMD480H12	SLMD480H12L
	SLMD481H08	SLMD481H08L
	SLMD481H10	SLMD481H10L
	SLMD481H12	SLMD481H12L
	SLMD600H10	SLMD600H10L
	SLMD960H12	SLMD960H12L

Reason: Switch from epoxy coating to lamination version due to higher reliability performance

Last time order date: Jun. 30th, 2012

Last time delivery date: Jul. 31st, 2012

Internal Reference: IKPO_2012_001

In case of any question, please contact

Initiator	Title/Function	Date	e-mail
Bill	MP	May. 20th, 2012	b.lee@ixys.net

IXYS Korea Ltd.
R&DB Center Suite#420, 906-5, Iui-Dong,
Yeongtong-Gu, Suwon, Gyeonggi-Do, Korea(443-766)
Phone: +82-31-888-5232
Fax: +82-31-888-5233

Customer response:

(Please fill in and return by e-mail, fax, or mail within 2 weeks)

☐ for further questions/information please comment

Company: _____

Name & Position: _____

Phone/Fax No.: _____

Comments: _____