Affected Products

Product Series	Mars ZX3
Affected Product Model	All product models
Affected Parts	[EN102150] MA-ZX3-20-1C-D9-R7 [EN102151] MA-ZX3-20-2I-D10-R7 [EN102877] MA-ZX3-20-2I-D10-ZB-R7
Replacement Parts	[EN104623] MA-ZX3-20-1C-D9-R7.1 [EN104624] MA-ZX3-20-2I-D10-R7.1 [EN104625] MA-ZX3-20-2I-D10-ZB-R7.1

Type of PCN, Description and expected impact for customers

Type of PCN	**A – Post on Enclustra Website** ☐ Removal of Product Model (if no customer is affected) ☐ Minor Revision without impact on customer ☐ Other, specify: **B – Inform current customers** ☐ Increase of minimum order quantity (MOQ) ☐ Status Changes to end-of-life (EOL) ☐ Removal of Product Model (if customer is affected) ☐ Major Revision roll-out ☒ Minor Revision with impact for customer ☐ Other, specify: **C – Inform all affected customers** ☐ Security related bug / Major non-conformance to specification ☐ Other, specify:
Description of change	Starting with the revision 7.1, the EEPROM with SHA-1 engine "DS28CN01" from Maxim is replaced by the EEPROM with Crypto Authentication "ATSHA204A-MAHDA-T" from Atmel. The new EEPROM has a different I2C address.
Reason for change	EOL component DS28CN01
Expected impact on customer	If the customer uses EEPROM then they need to adjust their software to the new I2C address.
Forecasted key milestones	Last Time Buy (LTB) date: N/A Last Time Ship (LTS) date: N/A

Details of change

Details	Refer to "Mars ZX3 User Manual" document available on Enclustra download site.

Contact

Details

If you have any questions or require additional information, please contact info@enclustra.com.
Web: www.enclustra.com