



# Product Change Notification

## TE Connectivity

Product Change Notification: P-20-018877

PCN Date: 03-APR-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

**General Product Description:**

Notification of packaging changes for -STK tubing products

**Description of Changes**

This is a notification informing TE Connectivity customers that the packaging boxes used for the tubing -STK products will be changing.

**Other attachments:**

[New Stick Boxes](#)

[PCN - Changes to Stick boxes](#)

[Stick parts for box changes](#)

**Reason for Changes:**

Product improvement. We are moving to a more robust design that will give better protection to the tubing products during transportation. The boxes are moving from a square profile to a rectangular one with different cardboard and latching method. We will be transitioning boxes as existing packaging is consumed so not all product will change at the same time.

**Estimated Dates:**

**Last Order Date** (Obsolete Parts Only): **First Date To Ship** (Changed Parts Only):

06-APR-2020

**Last Ship Date** (Obsolete Parts Only): **Last Date for Mixed Shipments:** (Changed Parts Only):

31-OCT-2020

**Part Number(s) being Modified:**

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">206247P038</a>	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">363884-000</a>	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
<a href="#">4429522003</a>	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5067592001</a>	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
<a href="#">5070022040</a>	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
<a href="#">5070082131</a>	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
<a href="#">5070122027</a>	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">5500042003</a>	NO			"5-1194328-8", "SCL-3/8-2-STK"			
<a href="#">5500102028</a>	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
<a href="#">5500192011</a>	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
<a href="#">5500282020</a>	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
<a href="#">5500312016</a>	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
<a href="#">5500692005</a>	NO			"TAT-125-1/4-0-STK", "1324239-2"			
<a href="#">5500702004</a>	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
<a href="#">5500712011</a>	NO			"1194336-2", "TAT-125-1/2-0-STK"			
<a href="#">5500722008</a>	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
<a href="#">5500732014</a>	NO			"7-1194336-1", "TAT-125-1-0-STK"			
<a href="#">5500742015</a>	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
<a href="#">5500752003</a>	NO			"2-1194337-2", "TAT-125-2-0-STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0-STK"			
<a href="#">5500962003</a>	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
<a href="#">5500982001</a>	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
<a href="#">5501052008</a>	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
<a href="#">5501062005</a>	NO			"7-1194339-5", "SCL-1-0-STK", "SCL-1-0-STK"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">581913P020</a>	NO			"1-1194610-0", "QS1500-NO.2-F6-0-STK"			
<a href="#">5978892002</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"4-1194727-5", "DWP-125-1-1/2-0-STK"			
<a href="#">6009112002</a>	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">636901P014</a>	NO			"8-1195035-6", "QS1500-NO.3-F7-0-STK"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">7580142002</a>	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
<a href="#">774185P009</a>	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">895231P008</a>	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">958133P007</a>	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
<a href="#">CB0929-000</a>	NO			"FL2500-NO.0-I7-0-STK"			
<a href="#">CV37322001</a>	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
<a href="#">CZ0181-000</a>	NO			"SCT-NO.5-Z4-0-STK"			
<a href="#">D20444-000</a>	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
<a href="#">E43149-000</a>	NO			"3-1199653-6", "FL2500-NO.2-I9-0-STK"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
<a href="#">EH2288-000</a>	NO			"DWFR-3/1-0-STK"			
<a href="#">EH2289-000</a>	NO			"DWFR-6/2-0-STK"			
<a href="#">EH2290-000</a>	NO			"DWFR-9/3-0-STK"			
<a href="#">EH2291-000</a>	NO			"DWFR-12/4-0-STK"			
<a href="#">EH2292-000</a>	NO			"DWFR-19/6-0-STK"			
<a href="#">EH2293-000</a>	NO			"DWFR-24/8-0-STK"			
<a href="#">EH2294-000</a>	NO			"DWFR-40/13-0-STK"			
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2296-000</a>	NO			"DWFR-8/2-0-STK"			
<a href="#">EH2297-000</a>	NO			"DWFR-12/3-0-STK"			
<a href="#">EH2298-000</a>	NO			"DWFR-16/4-0-STK"			
<a href="#">EH2299-000</a>	NO			"DWFR-24/6-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">EM63332001</a>	NO			"BATTU-12.7/6.1-A1-3-STK"			
<a href="#">EM63392001</a>	NO			"BATTU-20.1/8.9-A1-3-STK"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM63952001</a>	NO			"BATTU-12.7/6.1-A1-4-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">EM64392001</a>	NO			"BATTU-25.4/12.7-A1-4-STK"			
<a href="#">NB07072001</a>	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
<a href="#">NB07092001</a>	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
<a href="#">NB07112001</a>	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
<a href="#">NB07132001</a>	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
<a href="#">NB07152001</a>	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

## Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">206247P038</a>	NO			"2-1191495-7", "SCT-NO.4-E2-0-STK"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">363884-000</a>	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
<a href="#">4429522003</a>	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5070022040</a>	NO			"2-1193959-4", "RNF-100-1/16-CL-STK"			
<a href="#">5070082131</a>	NO			"2-1193965-3", "RNF-100-1/2-CL-STK"			
<a href="#">5070122027</a>	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">5500102028</a>	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
<a href="#">5500312016</a>	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
<a href="#">5500692005</a>	NO			"TAT-125-1/4-0-STK", "1324239-2"			
<a href="#">5500702004</a>	NO						

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
				"7-1194335-4", "TAT-125-3/8-0-STK"			
<a href="#">5500712011</a>	NO			"1194336-2", "TAT-125-1/2-0-STK"			
<a href="#">5500722008</a>	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
<a href="#">5500732014</a>	NO			"7-1194336-1", "TAT-125-1-0-STK"			
<a href="#">5500742015</a>	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
<a href="#">5500962003</a>	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
<a href="#">5500982001</a>	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
<a href="#">5501062005</a>	NO			"7-1194339-5", "SCL-1-0-STK", "SCL-1-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">6009112002</a>	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">7580142002</a>	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
<a href="#">EH2289-000</a>	NO			"DWFR-6/2-0-STK"			
<a href="#">EH2292-000</a>	NO			"DWFR-19/6-0-STK"			
<a href="#">EH2296-000</a>	NO			"DWFR-8/2-0-STK"			
<a href="#">EH2297-000</a>	NO			"DWFR-12/3-0-STK"			
<a href="#">EH2298-000</a>	NO			"DWFR-16/4-0-STK"			
<a href="#">EH2299-000</a>	NO			"DWFR-24/6-0-STK"			
<a href="#">EM63332001</a>	NO			"BATTU-12.7/6.1-A1-3-STK"			
<a href="#">EM63392001</a>	NO			"BATTU-20.1/8.9-A1-3-STK"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM63952001</a>	NO			"BATTU-12.7/6.1-A1-4-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">EM64392001</a>	NO			"BATTU-25.4/12.7-A1-4-STK"			
<a href="#">NB07072001</a>	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
<a href="#">NB07092001</a>	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
<a href="#">NB07112001</a>	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
<a href="#">NB07132001</a>	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
<a href="#">NB07152001</a>	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">063725P022</a>	NO			"6-1190481-1", "ES2000-NO.2-B9-0-STK", "ES2000-2-4FOOT"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">121397P024</a>	NO			"4-1190883-3", "ES2000-NO.3-B8-0-STK"			
<a href="#">130599P006</a>	NO			"6-1190948-4", "ES2000-NO.4-B7-0-STK"			
<a href="#">2951512003</a>	NO			"DWP-125-1/4-0-STK", "1448670-1", "16-0151"			
<a href="#">363884-000</a>	NO			"1-1199654-7", "FL2500-NO.3-J1-0-STK"			
<a href="#">4429522003</a>	NO			"6-1193329-8", "DWP-125-1/8-0-STK"			
<a href="#">5052842057</a>	NO			"3-1193821-9", "RNF-100-3/64-BK-STK"			
<a href="#">5052892107</a>	NO			"5-1193823-3", "RNF-100-1/16-BK-STK", "16-0112"			
<a href="#">5052942218</a>	NO			"1-1193827-7", "RNF-100-3/32-BK-STK"			
<a href="#">5052992172</a>	NO			"1-1193833-7", "RNF-100-1/8-BK-STK"			
<a href="#">5053042176</a>	NO			"8-1193838-6", "RNF-100-3/16-BK-STK"			
<a href="#">5053092267</a>	NO			"2-1193845-2", "RNF-100-1/4-BK-STK"			
<a href="#">5053142385</a>	NO			"2-1193853-6", "RNF-100-3/8-BK-STK"			
<a href="#">5053192266</a>	NO			"1-1193862-2", "RNF-100-1/2-BK-STK"			
<a href="#">5053242179</a>	NO			"1-1193869-9", "RNF-100-3/4-BK-STK"			
<a href="#">5053292160</a>	NO			"3-1193876-7", "RNF-100-1-BK-STK"			
<a href="#">5053392064</a>	NO			"7-1193885-6", "RNF-100-2-BK-STK"			
<a href="#">5053442033</a>	NO			"5-1193887-7", "RNF-100-3-BK-STK"			
<a href="#">5070122027</a>	NO			"5-1193969-9", "RNF-100-2-CL-STK"			
<a href="#">5076682002</a>	NO			"DWP-125-3/4-0-STK", "1448810-3"			
<a href="#">543633P064</a>	NO			"5-1194264-0", "SCT-NO.1-E6-0-STK"			
<a href="#">5500102028</a>	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
<a href="#">5500312016</a>	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
<a href="#">5500692005</a>	NO			"TAT-125-1/4-0-STK", "1324239-2"			
<a href="#">5500702004</a>	NO			"7-1194335-4", "TAT-125-3/8-0-STK"			
<a href="#">5500712011</a>	NO			"1194336-2", "TAT-125-1/2-0-STK"			
<a href="#">5500722008</a>	NO			"4-1194336-1", "TAT-125-3/4-0-STK", "1406806"			
<a href="#">5500732014</a>	NO			"7-1194336-1", "TAT-125-1-0-STK"			
<a href="#">5500742015</a>	NO			"1194337-3", "TAT-125-1-1/2-0-STK"			
<a href="#">5500962003</a>	NO			"3-1194338-0", "TAT-125-1/8-0-STK"			
<a href="#">5500982001</a>	NO			"3-1194338-9", "TAT-125-3/16-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">6009112002</a>	NO			"7-1194754-0", "DWP-125-3/16-0-STK"			
<a href="#">607381P046</a>	NO			"5-1194804-3", "SCT-NO.2-E5-0-STK"			
<a href="#">6465212003</a>	NO			"114517-01", "1448193-1", "DWP-125-1/2-0-STK", "16-0149"			
<a href="#">7580142002</a>	NO			"DWP-125-3/8-0-STK", "1448852-3", "16-0150"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">9346692002</a>	NO			"2-1197242-1", "DWP-125-1-0-STK"			
<a href="#">E95757-000</a>	NO			"4-1199653-3", "FL2500-NO.4-J2-0-STK"			
<a href="#">EH2289-000</a>	NO			"DWFR-6/2-0-STK"			
<a href="#">EH2296-000</a>	NO			"DWFR-8/2-0-STK"			
<a href="#">EH2297-000</a>	NO			"DWFR-12/3-0-STK"			
<a href="#">EH2298-000</a>	NO			"DWFR-16/4-0-STK"			
<a href="#">EH2299-000</a>	NO			"DWFR-24/6-0-STK"			
<a href="#">EM63332001</a>	NO			"BATTU-12.7/6.1-A1-3-STK"			
<a href="#">EM63392001</a>	NO			"BATTU-20.1/8.9-A1-3-STK"			
<a href="#">EM63602001</a>	NO			"BATTU-25.4/12.7-A1-3-STK"			
<a href="#">EM63952001</a>	NO			"BATTU-12.7/6.1-A1-4-STK"			
<a href="#">EM64322001</a>	NO			"BATTU-20.1/8.9-A1-4-STK"			
<a href="#">EM64392001</a>	NO			"BATTU-25.4/12.7-A1-4-STK"			
<a href="#">NB07072001</a>	NO			"BATTU-12.7/6.1-A1-0-STK", "8-1899840-5"			
<a href="#">NB07092001</a>	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
<a href="#">NB07112001</a>	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
<a href="#">NB07132001</a>	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
<a href="#">NB07152001</a>	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">5067592001</a>	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">5500042003</a>	NO			"5-1194328-8", "SCL-3/8-2-STK"			
<a href="#">5500102028</a>	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
<a href="#">5500192011</a>	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
<a href="#">5500282020</a>	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
<a href="#">5500312016</a>	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
<a href="#">5500752003</a>	NO			"2-1194337-2", "TAT-125-2-0-STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0-STK"			
<a href="#">5501052008</a>	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">581913P020</a>	NO			"1-1194610-0", "QS1500-NO 2-F6-0-STK"			
<a href="#">5978892002</a>	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
<a href="#">636901P014</a>	NO			"8-1195035-6", "QS1500-NO 3-F7-0-STK"			
<a href="#">774185P009</a>	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">958133P007</a>	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
<a href="#">CB0929-000</a>	NO			"FL2500-NO.0-I7-0-STK"			
<a href="#">CV37322001</a>	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
<a href="#">CZ0181-000</a>	NO			"SCT-NO.5-Z4-0-STK"			
<a href="#">D20444-000</a>	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
<a href="#">E43149-000</a>	NO			"3-1199653-6", "FL2500-NO 2-I9-0-STK"			
<a href="#">EH2288-000</a>	NO			"DWFR-3/1-0-STK"			
<a href="#">EH2289-000</a>	NO			"DWFR-6/2-0-STK"			
<a href="#">EH2290-000</a>	NO			"DWFR-9/3-0-STK"			
<a href="#">EH2291-000</a>	NO			"DWFR-12/4-0-STK"			
<a href="#">EH2292-000</a>	NO			"DWFR-19/6-0-STK"			
<a href="#">EH2293-000</a>	NO			"DWFR-24/8-0-STK"			
<a href="#">EH2294-000</a>	NO			"DWFR-40/13-0-STK"			
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2296-000</a>	NO			"DWFR-8/2-0-STK"			
<a href="#">EH2297-000</a>	NO			"DWFR-12/3-0-STK"			
<a href="#">EH2298-000</a>	NO			"DWFR-16/4-0-STK"			
<a href="#">EH2299-000</a>	NO			"DWFR-24/6-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">NB07092001</a>	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
<a href="#">NB07112001</a>	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
<a href="#">NB07132001</a>	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
<a href="#">NB07152001</a>	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			

Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">5053342101</a>	NO			"2-1193882-6", "RNF-100-1-1/2-BK-STK"			
<a href="#">829131P021</a>	NO			"7-1196474-9", "ES2000-NO.1-C1-0-STK"			



Part Number(s) being Modified:

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">035377P004</a>	NO			"4-1190273-8", "ES1000-NO.3-B8-X-STK"			
<a href="#">085193P003</a>	NO			"9-1190628-5", "ES1000-NO.4-B7-X-STK"			
<a href="#">193197P004</a>	NO			"4-1191401-7", "ES1000-NO.1-C1-X-STK"			
<a href="#">5067592001</a>	NO			"5-1193934-3", "TAT-125-3/4-2-STK"			
<a href="#">5233452001</a>	NO			"6-1194111-2", "DWP-125-3/8-2-STK"			
<a href="#">537637P041</a>	NO			"8-1194219-5", "SCT-NO.3-E3-0-STK"			
<a href="#">5500042003</a>	NO			"5-1194328-8", "SCL-3/8-2-STK"			
<a href="#">5500102028</a>	NO			"2-1194329-8", "SCL-1/8-0-STK", "SCL-1/8-0-STK"			
<a href="#">5500192011</a>	NO			"5-1194330-0", "SCL-3/8-0-STK", "SCL-3/8-0-STK"			
<a href="#">5500282020</a>	NO			"6-1194331-8", "SCL-3/16-0-STK", "SCL-3/16-0-STK"			
<a href="#">5500312016</a>	NO			"8-1194332-3", "SCL-1/2-0-STK", "SCL-1/2-0-STK"			
<a href="#">5500752003</a>	NO			"2-1194337-2", "TAT-125-2-0-STK"			
<a href="#">5500762006</a>	NO			"4-1194337-1", "TAT-125-3-0-STK"			
<a href="#">5501052008</a>	NO			"1-1194339-0", "SCL-3/4-0-STK", "SCL-3/4-0-STK"			
<a href="#">5501092019</a>	NO			"3-1194340-1", "SCL-1/4-0-STK", "SCL-1/4-0-STK"			
<a href="#">576105P004</a>	NO			"7-1194570-9", "ES1000-NO.2-B9-X-STK"			
<a href="#">581913P020</a>	NO			"1-1194610-0", "QS1500-NO 2-F6-0-STK"			
<a href="#">5978892002</a>	NO			"4-1194727-5", "DWP-125-1-1/2-0-STK"			
<a href="#">636901P014</a>	NO			"8-1195035-6", "QS1500-NO 3-F7-0-STK"			
<a href="#">774185P009</a>	NO			"8-1196028-7", "QS1500-NO.1-F5-0-STK"			
<a href="#">895231P008</a>	NO			"5-1196961-1", "SCT-NO.0-E8-0-STK"			
<a href="#">9170152001</a>	NO			"1-1197118-5", "DWP-125-2-0-STK"			
<a href="#">958133P007</a>	NO			"1197417-6", "QS1500-NO.4-F8-0-STK"			
<a href="#">CB0929-000</a>	NO			"FL2500-NO.0-I7-0-STK"			
<a href="#">CV37322001</a>	NO			"RW-175-E-1-X-STK", "3-1899810-8"			
<a href="#">CZ0181-000</a>	NO			"SCT-NO.5-Z4-0-STK"			
<a href="#">D20444-000</a>	NO			"1-1199653-5", "FL2500-NO.1-I8-0-STK"			
<a href="#">E43149-000</a>	NO			"3-1199653-6", "FL2500-NO 2-I9-0-STK"			
<a href="#">EH2288-000</a>	NO			"DWFR-3/1-0-STK"			
<a href="#">EH2289-000</a>	NO			"DWFR-6/2-0-STK"			
<a href="#">EH2290-000</a>	NO			"DWFR-9/3-0-STK"			
<a href="#">EH2291-000</a>	NO			"DWFR-12/4-0-STK"			
<a href="#">EH2292-000</a>	NO			"DWFR-19/6-0-STK"			
<a href="#">EH2293-000</a>	NO			"DWFR-24/8-0-STK"			
<a href="#">EH2294-000</a>	NO			"DWFR-40/13-0-STK"			
<a href="#">EH2295-000</a>	NO			"DWFR-4/1-0-STK"			
<a href="#">EH2296-000</a>	NO			"DWFR-8/2-0-STK"			
<a href="#">EH2297-000</a>	NO			"DWFR-12/3-0-STK"			
<a href="#">EH2298-000</a>	NO			"DWFR-16/4-0-STK"			
<a href="#">EH2299-000</a>	NO			"DWFR-24/6-0-STK"			
<a href="#">EH2300-000</a>	NO			"DWFR-32/8-0-STK"			

Part Number	Part Discontinued per PCN	Customer Drawing	Customer Part Number	Alias Part Number(s)	Substitute Part Number	Substitute Alias Part Number(s)	Description Of Difference
<a href="#">EH2301-000</a>	NO			"DWFR-52/13-0-STK"			
<a href="#">NB07092001</a>	NO			"BATTU-12.7/6.1-A1-2-STK", "8-1899840-3"			
<a href="#">NB07112001</a>	NO			"BATTU-20.1/8.9-A1-0-STK", "8-1899840-1"			
<a href="#">NB07132001</a>	NO			"BATTU-20.1/8.9-A1-2-STK", "7-1899840-9"			
<a href="#">NB07152001</a>	NO			"BATTU-25.4/12.7-A1-0-STK", "7-1899840-7"			
<a href="#">NB07172001</a>	NO			"BATTU-25.4/12.7-A1-2-STK", "7-1899840-6"			