

Global Change Notification (GCN)

Product Family	Mini Fit	10641457
		GCN Number
Series	5566	July 03, 2014
		Date Issued
Reason For Change	New, Modified, Or Replacement Tooling	
Change Description	The mold that makes 5566-06 housings has reached end of life. Molex is currently building a new mold to replace the existing mold.	
Part Numbers Affected	Please refer to CustomerPartList.csv attached to e-mail message.	
Reason For Short Notice Exception	Force Majeure	
Assessment Of Change (How Product Will Be Qualified & Validated)	The new mold will be fully qualified before it is put into production.	
Internal Molex Qualification Date (Planned Date Information Available)	July 23, 2014	
Sample Availability Date (Changed Part)	July 23, 2014	
Date of Implementation	July 30, 2014	
Method of Identifying Change	Housings molded after July 30, 2014	
Recommended Replacement Parts	Not Applicable	
Last Time Buy Date for Obsolete Parts		
Last Time Ship Date for Obsolete Parts		

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com

39281063
39288060
39290063
39293066
39296068
39310060
39310067
39310068
39350068
444720654
444720655
460150602
39293068
39295066
39295067
39333063
39333064
39333066
39338067
39338068
39341060
98013065
98264066
98265063
98278064
98278065
98278067
98282069
444720656
444720657
469990140
39306062
50361668
435880024
460150606
885101600
885129200
885148400
885148500
885161500
885176300
39539068
98268069
435880020
460150600
460150604
469990566

799170074
799180125
435880025