
## **Amphenol Canada Corp - Product Change Notice (PCN)**

PCN Date	December 16, 2016
Supplier Name:	Amphenol Canada Corp.
Amphenol Canada PCN Number	PCN-C1287
Description of Change	Part Modification
Reason for Change	Modifications made to improve PCB solder process
Summary of changes between new and old part	see below
Traceability guidelines (lot code / date code,	Date code
markings, ship date)	Date code
Last Time Buy Date	Not Applicable
Datasheet attached? & Filename(s)	
Qual Test data attached? & Filename(s)	Not Required

Customer Part Number	Amphenol Old Part Number	Amphenol New Part Number	Effectivity	ΔVallahilitV	Last Time Buy	Return Date (If	Expected Supplier Qual Date
	12401562E4#2A	12401562E4#2A	16-Dec-16	as required	Not Applicable	Jan 31-2017	
					_		



After change

1.add the plastic wall to fixed the PCB, easy to solder process
2.moved the latch solder pin to another side.

## 7.60 B

## Influence

There will be a limitation on PCB width which should be within 7.6mm

