

TE Connectivity

Product Change Notification: E-20-007210 PCN Date: 10-SEP-20

TE would like to inform you of the following change(s) to the listed TE Connectivity Product. In case of any further questions about this change(s), please contact your TE Connectivity Sales Engineer. Affected part, drawing and/or specification numbers are listed on the attached sheet(s).

General Product Description:
SDE Commercial hand tool locator update.

Description of Changes

SDE commercial hand tools are being updated with a new design terminal locator. The redesigned locator functions the same as the previous design but allows easier adjustments of the terminal support blade. Hand tools already in the field do not need updated as the function has not changed.

| Reason for Changes: | | | | | | |
|--|--|--|--|--|--|--|
| Product Improvement. | roduct Improvement. | | | | | |
| Estimated Dates: | | | | | | |
| Last Order Date (Obsolete Parts Only): | First Date To Ship (Changed Parts Only): | | | | | |
| | 25-SEP-2020 | | | | | |
| Last Ship Date (Obsolete Parts Only): | Last Date for Mixed Shipments: (Changed Parts Only): | | | | | |
| | 01-NOV-2020 | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 1976144-1 | NO | | | . , | | , | |
| 58590-1 | NO | | | | | | |
| 58605-1 | NO | | | | | | |
| 58605-2 | NO | | | | | | |
| 91391-1 | NO | | | | | | |
| <u>91391-2</u> | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 1976144-1 | NO | | | | | | |
| <u>58590-1</u> | NO | | | | | | |
| <u>58605-1</u> | NO | | | | | | |
| 58605-2 | NO | | | | | | |
| <u>91391-1</u> | NO | | | | | | |
| 91391-2 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|----------------|---------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| 91391-1 | NO | | | | | | |

Part Number(s) being Modified:

| Part Number | Part Discontinued per PCN | Customer Drawing | Customer Part Number | Alias Part Number(s) | Substitute Part Number | Substitute Alias Part Number(s) | Description Of Difference |
|-------------------|------------------------------|---------------------|-------------------------|-------------------------|---------------------------|------------------------------------|------------------------------|
| <u> 1976144-1</u> | NO | | | | | | |
| <u>58590-1</u> | NO | | | | | | |
| <u>58605-1</u> | NO | | | | | | |
| <u>58605-2</u> | NO | | | | | | |
| 91391-1 | NO | | | | | | |
| 91391-2 | NO | | | | | | |