



RF-403-002 August 16, 2011

Overview

The purpose of this notification is to communicate that OmniVision Technologies, Inc. (OVT) is discontinuing product(s) identified below. The timeline and terms and conditions associated with the product discontinuance are contained within this notification.

Description

The demand for the products contained in this notification has significantly declined. A more cost effective device with more features and improved performance metrics is available as a superior replacement. Omnivision Technologies is discontinuing these devices to ensure we manage our inventory and supply chain to offer our customers the best level of service as well as the most economic supply chain.

Product(s) Affected

Please see attached table.

Timeline

Effective Date: August 16, 2011

Last Time Order Date: February 16, 2012 (6 months from PDN notification)

Last Time Ship Date: August 16, 2012 (6 months from Last Time Order date; 1 year

from PDN notification.

OVT will continue to accept orders for products contained in this notification between the effective date and last time order date noted above. During this period, all orders will be subject to non-cancelable, non-returnable (NCNR) terms. After the last time order date, OVT will no longer accept new orders for any product contained in this notification.


OVT will discontinue shipment of all products contained in this notification after the last time ship date noted above. All orders for these products must request delivery on or prior to the last time ship date.

Response

No response is required to this notification. For additional information regarding this notification, please contact your local OmniVision Technologies, Inc. Sales Representative.

This notification can also be found on www.ovt.com/support. The notification link will be located on the bottom right hand corner of the web page.

www.ovt.com/support Page 1 of 3





RF-403-002 August 16, 2011

OVT Part Number	Replacement Device
OVM2665-N60A	Please See Note 1.
OVM2665-N60B	Please See Note 1.
OVM2665-N60C	Please See Note 1.
OVM2665-N60D	Please See Note 1.
OVM2665-R60A-4A	Please See Note 1.
OVM2665-R60B-4A	Please See Note 1.
OVM2665-R60C-4A	Please See Note 1.
OVM2665-RYBA	Please See Note 1.
OVM2665-R60A	Please See Note 1.
OVM2665-R60B	Please See Note 1.
OVM2665-R60C	Please See Note 1.
OVM2665-R60D	Please See Note 1.
OVM2665-LCA1	Please See Note 1.
OVM2665-LCA1-D	Please See Note 1.
OVM2665-R60A-4A-Z	Please See Note 1.
OVM2665-RYBA-Z	Please See Note 1.
OVM2665-EAAR-AA0A	Please See Note 1.
OVM2665-ECJA-BA0A	Please See Note 1.
OVM2665-ETJR-BA0A	Please See Note 1.
OV02715-A68A-1D	Please See Note 1.
OV02715-A68A-1D-Z	Please See Note 1.
OV05633-T48A	Please See Note 1.
OV05633-T48B	Please See Note 1.
OV05633-T48C	Please See Note 1.
OV05633-T48A-Z	Please See Note 1.
OV06650-L22A	Please See Note 1.
OV06650-L22B	Please See Note 1.
OV06650-L22C	Please See Note 1.
OV06650-EAAA-AA0A	Please See Note 1.
OV06650-ECFA-BA0A	Please See Note 1.
OV06650-ECXA-BA0A	Please See Note 1.
OV06650-ECXF-BA1A	Please See Note 1.
OV06650-ETXA-BA0A	Please See Note 1.
OV06650-MFSG-F400	Please See Note 1.
OV07737-G04A	Please See Note 1.
OV07737-G04B	Please See Note 1.
OV07737-G04A-BV	Please See Note 1.



Product Discontinuance Notification

RF-403-002 August 16, 2011

OV07737-A20T	Please See Note 1.
OV07737-A20A	Please See Note 1.
OV07737-A20B	Please See Note 1.
OV07737-A20C	Please See Note 1.
OV07737-G04A-Z	Please See Note 1.
OV07949-Q48W	Please See Note 1.
OV07949-Q48V	Please See Note 1.
OV07949-Q48P	Please See Note 1.
OV07949-Q48N	Please See Note 1.
OV07949-Q48B	Please See Note 1.
OV07949-Q48C	Please See Note 1.
OV09655-V28T	Please See Note 1.
OV00519-T64G	Please See Note 1.
OV00531-B88G	Please See Note 1.
OV00535-B88G	Please See Note 1.
OV00630-B64G	Please See Note 1.
OV00810-W	Please See Note 1.
OV00811-W	Please See Note 1.
OV00812-W	Please See Note 1.
OV00720-B02G	Please See Note 1.
OVC6001-P16G-1S	Please See Note 1.
OVC6001-G20X	Please See Note 1.
OVC6300-T20G-1S	Please See Note 1.
OVC6300-T20G	Please See Note 1.

Note 1. Please contact your local Sales Representative for assistance with identifying a suitable replacement device.

www.ovt.com/support Page 3 of 3