## Product Changes Information Letter

Form 46.01.13 V2 / 2015-03-18

Information Letter Number: 220801			Date: 23/02/2022	
Title: SEN5x firmware up	date			
Product Identification: S	SEN54-SDN-T ( <b>3.000.535)</b> , S	SEK-SEN5x (3.000.670)		
Reason for Change:	☐ Design	☐ Production	☐ Logistics	
	☐ Manufacturing Location	☐ Quality/Reliability	☑ Upgrade	
Change Description:				
ment.	new firmware version with the nent mode.	•	ement, and RHT/Gas-Only Measure- th between measurement mode and	
compatible with the origin	al version.  Distinguish Change:	ensor's operation, and the ne	w firmware version is fully backward	
Identification Method to Change in the firmware vo	Distinguish Change: ersion, from v1.0 to v2.0.	ensor's operation, and the ne □ will be available in	w firmware version is fully backward	
Identification Method to Change in the firmware vo	Distinguish Change: ersion, from v1.0 to v2.0.			
Identification Method to Change in the firmware volume Samples:  Quantifiable Impact on 0	Distinguish Change: ersion, from v1.0 to v2.0.			
Identification Method to Change in the firmware volume Samples:  Quantifiable Impact on Company of the Company	Distinguish Change: ersion, from v1.0 to v2.0.  available  Quality & Reliability: none  on Date*: 15. March 2022	□ will be available in		

If you have questions with regard to this Information Letter, please send them to the Sensirion contact e-mail address listed above.