Micron Technology, Inc. 8000 S. Federal Way PO Box 6 Boise, ID United States

# 7100 Firmware Update to PA00MU05

## PCN: 32234

## Published: 2017-02-27

Туре:	Firmware Revision			
Description:	New firmware release for 7100			
		cted an issue w n of the drive m	here firmware reported a truncated nodel number.	
Anticipated Impact: Quality improvement: Corrected reporting of model number				
Reason:	Improved Pre	oduct Quality ar	nd Reliability	
Product Affected:	7100 ECO a	nd 7100 MAX		
Affected Micron Part	Number	Recommended Replacement	Customer Part Number	
<u>Component</u>				
MTFDHAK1T6MCG-	1AN1ZABYY			
MTFDHAK1T9MCH-	1AN1ZABYY			
MTFDHAK400MCG-	1AN1ZABYY			
MTFDHAK480MCH-	1AN1ZABYY			
MTFDHAK800MCG-	1AN1ZABYY			
MTFDHAK960MCH-	1AN1ZABYY			
MTFDHBG400MCG-	1AN1ZABYY			
MTFDHBG480MCH	-1AN1ZABYY	7	MTFDHBG480MCH-1AN1ZABYY- ND	
MTFDHBG800MCG-	1AN1ZABYY			
MTFDHBG960MCH-	1AN1ZABYY			

\*Materials that have been ordered are in **bold**.

Method of Identification:	Firmware is printed on product label and accessible electronically via identify commands		
Micron Sites Affected:	Subcontractor		
Qualification Plan:	Firmware validation has completed.		
Sample Available:	2017-02-27		
Qual Data Available:	2017-02-22		
Product Ship Data:	2017 02 20		

### Product Ship Date: 2017-03-29

NOTE: Per JEDEC Standard JESD46-C Section 3.2.3; lack of acknowledgment of this PCN within 30 days constitutes acceptance of change.

#### **Micron Confidential and Proprietary Information**

#### Thank you

Legal Disclaimer: The information contained in this message may be privileged and confidential. It is intended to be read only by the individual or entity to whom it is addressed or by their designee. If the reader of this message is not the intended recipient, you are on notice that any distribution of this message, in any form, is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete or destroy any copy of this message.