

PRODUCT CHANGE NOTIFICATION **Product Category RACKS** 20191119-1 **ROAR Product Group** ISSUE DATE: 20191209 **IMPACTED REGIONS:** \square NA ✓ EMEA ✓ LATAM **∠** AP **REASON FOR CHANGE:** UDISCONTINUATION OTHER **DESCRIPTION OF CHANGE: (Required)** Discontinuation for R4P42WH/N. Non-standard version is discontinued and replaced with a standard product. IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable) Reference Page 2 / Linked PDF DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:

	Year	Month	Day
SCHEDULE FOR CHANGE	(YYYY)	(MM)	(DD)
New product sample availability date	2019	11	25
Old product discontinuation date*	2020	3	9

^{*}Important: A return material authorization (RMA) may be obtained for the affected part numbers listed above if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

IMPACTED PART NUMBER(s)	Replacement Part
INIT ACTED TART NONDER(5)	Replacement rate
R4P42WH/N	R4P42WH
	<u> </u>