

Enclustra - Product Change Notification (PCN)

No.:	PCN_SP_2021-001
Date:	01.04.2021

Affected Product series	
Product Series	Mars ST3
Affected Configuration	MA-ST3 MA-ST3-X1
Affected Parts	[EN102462] MA-ST3-R1.1 [EN102556] MA-ST3-X1-R1.1
Replacement Parts	[EN103242] MA-ST3-W-R2

Type of PCN, Description and expected impact for customers		
Type of PCN	A – Post on Enclustra Website	
	☐ Removal of Product Configuration (if no customer is affected)	
	☐ Minor Revision without impact on customer	
	☐ Other, specify:	
	B – Inform current customers	
	☐ Increase of minimum order quantity (MOQ)	
	☐ Product Status Changes to end-of-life (EOL)	
	☐ Removal of Product Configuration (if customer is affected)	
	☑ Major Revision roll-out	
	☐ Minor Revision with impact for customer	
	☐ Other, specify:	
	C – Inform all affected customers	
	☐ Security related bug / Major non-conformance to specification	
	☐ Other, specify:	
Description of change	Various bug fixes and improvements – mechanical and electrical changes	
	Module connector pinout changes	
	Changes related to IO voltage configuration circuit and DIP switches	
	New features: optional watchdog circuit, MIPI DSI support	
Reason for change	Bug fixes and improvements	
	Added new features	
Expected impact on customer	Depending on used interfaces, an updated boot image/bitstream for the Enclustra module may be	
	required.	
	After stock depletion of affected parts (R1.1), only replacement parts (R2) will be delivered.	
Forecasted key milestones	Last Time Buy (LTB) date: see above	
rorecasted key innestories	Last Time Ship (LTS) date: see above	

Details of change	
Details	Refer to "Mars ST3 R2 Known Issues and Changes" document available on Enclustra download site.

Contact

Details

If you have any questions or require additional information, please contact info@enclustra.com.

Web: www.enclustra.com

Template No: ED42010-01 Page 1 of 1