



March 7, 2016

Cinch Authorized Distributors:

Due to tooling/die issues, Cinch can no longer supply the 300 Series Jones sockets, part numbers listed below. Effective immediately, these part numbers are discontinued. Please make the appropriate changes in your system. If you have any of the discontinued part numbers in your inventory and wish to return them, you have 30 days to request an RMA. The parts will need to be functional and purchased from Cinch within the last two years.

The part number effected are:

S302CCT	S302FP	S302HAB	S302HCCT
S302HCCTK	S303FP	S303HAB	S303HCCT
S303HLAB	S304CCT	S304CCTK	S304DB
S304HAB	S304HCCT	S304CCTK	S306CCT
S306FP	S306HAB	S306HCCT	S306HLAB
S306LAB	S315AB	S315CCT	S318CCT
S202B	S202CCT	S202CCTTHR	

Cinch apologizes for any inconvenience this may cause you or your customers. Please feel free to contact me if you have any questions.

Thank you,

Pam Bauch

Product Service Manager

1700 Finley Road
Lombard, IL
60148 USA

cinch.com