

Global Change Notification (GCN)

Product Family .093" Pin and Socket receptacle Housing 10646585


GCN Number

Series 1360-R1 July 24, 2014


Date Issued

Reason For Change Obsolescence

Change Description The mold used to make housing 1360-R1 (3091122) housings is worn beyond repair and is being taken out of service. Housing part number 3091126 can be used as a replacement with a passive locking ramp. The replacement should be reviewed by the customer for suitability.



Current housing



Proposed replacement housing

Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message.

Reason For Short Notice Exception Force Majeure

Assessment Of Change (How Product Will Be Qualified & Validated)

Internal Molex Qualification Date (Planned Date Information Available) September 30, 2014

Sample Availability Date (Changed Part) September 30, 2014

Date of Implementation September 30, 2014

Method of Identifying Change Not Applicable

Recommended Replacement Parts 3091126

Last Time Buy Date for Obsolete Parts September 30, 2014

Last Time Ship Date for Obsolete Parts October 31, 2014

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	QuiNann Lim	QuiNann.Lim@molex.com	+31-40-295-8472
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc.
 2222 Wellington Court
 Lisle, IL 60532
 TEL: 630-969-4747
www.molex.com