


PCN Number:	20160204002	PCN Date:	2/16/2016
Title:	Datasheet for LM5066		
Customer Contact:	PCN Manager	Dept:	Quality Services
Change Type:			
<input type="checkbox"/>	Assembly Site	<input type="checkbox"/>	Design
<input type="checkbox"/>	Assembly Process	<input checked="" type="checkbox"/>	Data Sheet
<input type="checkbox"/>	Assembly Materials	<input type="checkbox"/>	Part number change
<input type="checkbox"/>	Mechanical Specification	<input type="checkbox"/>	Test Site
<input type="checkbox"/>	Packing/Shipping/Labeling	<input type="checkbox"/>	Test Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Material
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Bump Process
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Site
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Materials
<input type="checkbox"/>		<input type="checkbox"/>	Wafer Fab Process
Notification Details			
Description of Change:			
Texas Instruments Incorporated is announcing an information only notification etc.			
The product datasheet(s) is being updated as summarized below.			
The following change history provides further details.			
		LM5066 <small>SNVS655I – JUNE 2011 – REVISED JANUARY 2016</small>	
Changes from Revision H (July 2014) to Revision I			Page
<ul style="list-style-type: none"> Changed V_{GATEZ} MIN value in <i>Electrical Characteristics</i> From: 15 V To: 12 V 			7
The datasheet number will be changing.			
Device Family	Change From:	Change To:	
LM5066	SNVS655H	SNVS655I	
These changes may be reviewed at the datasheet links provided. http://www.ti.com/product/LM5066			
Reason for Change:			
To more accurately reflect device characteristics.			
Anticipated impact on Fit, Form, Function, Quality or Reliability (positive / negative):			
No anticipated impact. This is a specification change announcement only. There are no changes to the actual device.			
Changes to product identification resulting from this PCN:			
None.			
Product Affected:			
LM5066PMH/NOPB	LM5066PMHE/NOPB	LM5066PMHX/NOPB	

For questions regarding this notice, e-mails can be sent to the regional contacts shown below or your local Field Sales Representative.

Location	E-Mail
USA	PCNAmericasContact@list.ti.com
Europe	PCNEuropeContact@list.ti.com
Asia Pacific	PCNAsiaContact@list.ti.com
Japan	PCNJapanContact@list.ti.com