

## IloT Product Change Notice



The change will be applied on the ULI-351DK (BB-BB-485USB9F-4W-LS). If you need more information or special support, please contact the corresponding PMs/AEs listed in the table below.

**Note: The ordering process has not been changed. Customers should continue to order model number BB-485USB9F-4W-LS.**

- Reason for the Change:** Branding.
- Affected Products:** ULI-351DK (BB-485USB9F-4W-LS)
- Impact on Application:** No change to form, fit, or function.

| Item                                  | Impact                   |
|---------------------------------------|--------------------------|
| Impact on Mechanical Design           | No                       |
| Impact on Software Compatibility      | No                       |
| Impact on Environment Characteristics | No                       |
| Impact on System Certifications       | No                       |
| Physical Outlook Change               | <b>Yes</b>               |
| Ordering P/N Change                   | No                       |
| Cut-in Implement                      | Component Running Change |

#### 4. Description of the Change(s):

| Affected Models                | Current Component    | New Component  | Category | Outlook Difference  | Reason   |
|--------------------------------|----------------------|----------------|----------|---|----------|
| ULI-351DK<br>BB-485USB9F-4W-LS | 20BB250-<br>10885-00 | 1990034354TOJO | Label    | <p>Old name plate</p>  <p>New name plate</p>  | Branding |

#### 5. Implementation & Schedule of the Change(s):

| Affected Models               | ECOM Number | Estimated Effective Date | Cut-in Implement | Change Description |
|-------------------------------|-------------|--------------------------|------------------|--------------------|
| ULI-351DK (BB-485USB9F-4W-LS) | ECOM-195123 | 12/30/2022               | Running Change   | Update name plate  |

\*Note: Cut-in progress depends on factory production schedule.

\*\* Note: The ordering process has not been changed. Customers should continue to order model number BB-485USB9F-4W-LS

## Contact Windows

|    |   |
|----|---|
| PM | Brian Foster / <a href="mailto:brian.foster@advantech.com">brian.foster@advantech.com</a> |
| AE | N/A   |