

Old - No Key Pin Installed

## **Global Change Notification (GCN)**

**Product Family VHDM** 10670113 **GCN Number** Series Various February 06, 2015 Date Issued Reason For Change Upgrade / Rearrangement Of Tooling / Equipment Change Description This letter is to inform you that we are making a change on the lead in to the plastic housing to reduce the amount of debris created during guide and key pin insertion. This change won't affect the functionality (mechanical & electrical) of parts and no qualification is needed. Old - No Guide Pin Installed New - No Key Pin Installed New - No Guide Pin Installed 10670113before.jpg If a connector has both a Guide & Key Pin, the change will not be noticeable 10670113after.jpg Part Numbers Affected Please refer to CustomerPartList.csv attached to e-mail message. Reason For Short Notice Exception 8D Corrective Action Changes Product will be qualified. Assessment Of Change (How Product Will Be Qualified & Validated) Internal Molex Qualification Date January 15, 2015 (Planned Date Information Available) Sample Availability Date February 16, 2015 (Changed Part) Date of Implementation February 16, 2015 Method of Identifying Change Parts manufactured after implementation date Recommended Replacement Parts N/A Last Time Buy Date for Obsolete Parts

Last Time Ship Date for Obsolete Parts

Contact	Name	E-mail	Phone Number
Sales Engineer	Please refer to e-mail message for your local sales engineer.		
Regional Coordinator (Japan and Korea)	Naomi Maruyama	Naomi.Maruyama@molex.co.jp	+81-46-265-2416
Regional Coordinator (Asia- excluding Japan and Korea)	Allen Yu	Allen.Yu@molex.com	+886-2-66251751
Regional Coordinator (Europe, Middle East, Africa)	Agnes Mburu	Agnes.Mburu@molex.com	+31-40-295-8271
Regional Coordinator (Americas)	Maria Sullivan	Maria.Sullivan@molex.com	1-727-322-4352

Molex, Inc. 2222 Wellington Court Lisle, IL 60532 TEL: 630-969-4747 www.molex.com