

INTERSIL CORPORATION
1650 Robert J. Conlan Blvd.
Palm Bay, FL 32905

May 12, 2015

Dear Valued Customer,

This letter is to inform you that the following parts will be moved back to active status and will continue to be supported through our production process.


ISL32613EFHZ-T, ISL32613EFHZ-T7A
ISL32614EFHZ-T, ISL32614EFHZ-T7A

The wafer fab process will migrate from our IBM foundry to our own internal wafer fab located in Palm Bay Florida. The migration of the parts above will not take place until 2016.

These parts are very general purpose and will be in production for a very long time.

Thank you for designing in these products. My sincere apologies for the disruption that we may have caused.

Very Sincerely,



Randy Pitts

Interface Product Line Marketing Manager

intersil[™]