

1 Products affected

| Product hierarchy no. * | | | | Part no. | SBU | Type / Description | Customer part no. |
|--|---------------|---------------|---------------|----------------|------------|--------------------|-------------------|
| SBU | PG | PUG | Type | | | | |
| 02 | 005 | 016 | 0000001109 | See list below | Connectors | KE (screw-on) | |
| <small>*SBU (2-digit) / PG (3-digit) / PUG (3-digit) / Type (10-digit)</small> | | | | | | | |
| KE10.2100.151 | KE10.6100.151 | KE15.1100.151 | KE16.5200.151 | KE20.6100.151 | KE60.0002 | | |
| KE10.2200.151 | KE10.6200.151 | KE16.5100.151 | KE20.2100.151 | KE60.0001 | | | |

2 Type of change

Change of approval markings from UR and CSA to the combined cURus on the part numbers with a socket for screw-on mounting.

3 Detailed description of change



4 Reason of change

The change is due to a standard update to UL/CSA 60320-1.

5 Release date

The change takes effect in ww49/2019 (Date code 1949 or higher on label). The validity of the approval certificates is not affected by this change.

6 Impact of change and recommended action

| | | |
|---------------|-----|---|
| Form | Yes | Socket new with cURus approval marking (@ 10A 250VAC) |
| Fit | No | - |
| Function | No | - |
| Manufacturing | No | - |
| Label | No | - |
| Packaging | No | - |

7 Reference Documents / Attachments

| Kind of document | Remarks |
|-------------------------------|---------|
| Data Sheet KE | |

| Product Change Notification | | | | | PCN KE | | D10-040-930 |
|-----------------------------|---------------|--------------|-------------|-----------------|--------|--------|-------------|
| owner | creation date | release date | released by | change order no | rev | page | |
| huberth | 08.11.2019 | 04.12.2019 | limachcl | 2018703 | A | 1 of 1 | |