

CUSTOMER	CUSTOMER DRAWING OR PART NUMBER		REV. NO.	TODAYS DATE
				2/1/2019
JKL PART NUMBER(s)	PART DESCRIPTION		Part Family	
3149	T-1 3/4 Bi Pin Lamp, 5V		T-1 3/4 Bi Pin	
JKL CONTACT NAME	PHONE	EMAIL:		

RF	ASON	FOR	NOT	ICE:

This lamp is no longer being produced. It is limited to stock on hand.

Obsolete Item:	Suggested Replacement Item:	
3149	7362	
This lamp is rated at:	The suggested replacement lamp is rated at:	
5V .060A .150 MSCP	5V .115A .150 MSCP (slightly higher current)	
	This lamp is mechanically equivalent.	