Product Discontinuation



PD_051_21

📕 La:	st Order Date:	2022-06-15
La:	st Delivery Date:	2023-06-15

Reason: Products have reached end of life

DISCONTINUED				NEW (REPLACEMENT)			
Sales Name	SP Number	OPN	Package	Sales Name	SP Number	OPN	Package
BSM100GAL120DLCK	SP000100477	BSM100GAL120DLCKHOSA1	AG-34MM	FD150R12RT4	SP000711858	FD150R12RT4HOSA1	AG-34MM
BSM100GB120DLCK	SP000095924	BSM100GB120DLCKHOSA1	AG-34MM	FF100R12RT4	SP000624754	FF100R12RT4HOSA1	AG-34MM
BSM100GB120DN2K	SP000101733	BSM100GB120DN2KHOSA1	AG-34MM	FF100R12RT4	SP000624754	FF100R12RT4HOSA1	AG-34MM
BSM35GB120DN2	SP000100461	BSM35GB120DN2HOSA1	AG-34MM	FF50R12RT4	SP000624912	FF50R12RT4HOSA1	AG-34MM
BSM50GAL120DN2	SP000101727	BSM50GAL120DN2HOSA1	AG-34MM	FD150R12RT4	SP000711858	FD150R12RT4HOSA1	AG-34MM
BSM50GB120DLC	SP000100474	BSM50GB120DLCHOSA1	AG-34MM	FF50R12RT4	SP000624912	FF50R12RT4HOSA1	AG-34MM
BSM50GB120DN2	SP000095922	BSM50GB120DN2HOSA1	AG-34MM	FF50R12RT4	SP000624912	FF50R12RT4HOSA1	AG-34MM
BSM75GAL120DN2	SP000106455	BSM75GAL120DN2HOSA1	AG-34MM	FD150R12RT4	SP000711858	FD150R12RT4HOSA1	AG-34MM
BSM75GAR120DN2	SP000100462	BSM75GAR120DN2HOSA1	AG-34MM	DF150R12RT4	SP000711868	DF150R12RT4HOSA1	AG-34MM
BSM75GB120DLC	SP000100473	BSM75GB120DLCHOSA1	AG-34MM	FF75R12RT4	SP000624916	FF75R12RT4HOSA1	AG-34MM
BSM75GB120DN2	SP000095923	BSM75GB120DN2HOSA1	AG-34MM	FF75R12RT4	SP000624916	FF75R12RT4HOSA1	AG-34MM

If you have any questions, please do not hesitate to contact your local sales office.

Disclaimer: The supply of this product will stop after the date of last delivery as outlined herein. Final orders can only be accepted on or before the last order date and are subject to the availability. Early ordering is strongly recommended! If Infineon confirms a purchase order with a delivery date beyond last delivery date, the PD with the mentioned last ordering date still remains valid.