

# PRODUCT CHANGE NOTIFICATION

Product Category COPPER QUICKNET & HIGH SPEED **20200610-01**

Product Group CONNECTIVITY & PATHWAYS

ISSUE DATE: 20200610

IMPACTED REGIONS:  NA  EMEA  LATAM  AP

REASON FOR CHANGE:  DISCONTINUATION  
 OTHER

**DESCRIPTION OF CHANGE: (Required)**

Panduit's Direct Attach Copper Cable Assemblies are going through a design change. This change will affect our SFP+ 10G and SFP28 25G products.

Packaging - The new product will be delivered in ESD safe packaging material

Pull Tab - Design and color changes to the pull tab allow for quick identification. SFP+ will have a dark blue tab; SFP28 will have a light blue pull tab.

Part Number - The part numbers will be updated to accompany these changes. See attached list.

Photos/Drawing (where applicable)

**IMPACTED PART NUMBERS AND REPLACEMENT PART NUMBERS: (where applicable)**

[Reference Page 2 / Linked PDF](#)

**DATES: DISCONTINUATION AND NEW PRODUCT AVAILABILITY:**

SCHEDULE FOR CHANGE	Year (YYYY)	Month (MM)	Day (DD)
New product sample availability date	2020	8	23
Old product discontinuation date*	2020	9	23

**\*Important:** A return material authorization (RMA) may be obtained for these affected part numbers and they may be returned up to 60 days after the product discontinuation announcement date if purchased within the last 18 months and subject to the return policy requirements outlined in Panduit's 1/1/19 Authorized Distributor Policy. Please contact your local Panduit Customer Experience team if you have any questions.

<b>IMPACTED PART NUMBER(s)</b>	<b>Type</b>	<b>Replacement Part 1</b>
PSF1PXA0.5MBL	No Replacement	
PSF1PXA0.5MBU	No Replacement	
PSF1PXA0.5MRD	No Replacement	
PSF1PXA0.5MWH	No Replacement	
PSF1PXA1.5MBL	Direct Replacement	PSF1PZA1.5MBL
PSF1PXA1.5MBU	Direct Replacement	PSF1PZA1.5MBU
PSF1PXA1.5MRD	Direct Replacement	PSF1PZA1.5MRD
PSF1PXA1.5MWH	Direct Replacement	PSF1PZA1.5MWH
PSF1PXA1MBL	Direct Replacement	PSF1PZA1MBL
PSF1PXA1MBU	Direct Replacement	PSF1PZA1MBU
PSF1PXA1MRD	Direct Replacement	PSF1PZA1MRD
PSF1PXA1MWH	Direct Replacement	PSF1PZA1MWH
PSF1PXA2.5MBL	Direct Replacement	PSF1PZA2.5MBL
PSF1PXA2.5MBU	Direct Replacement	PSF1PZA2.5MBU
PSF1PXA2.5MRD	Direct Replacement	PSF1PZA2.5MRD
PSF1PXA2.5MWH	Direct Replacement	PSF1PZA2.5MWH
PSF1PXA2MBL	Direct Replacement	PSF1PZA2MBL
PSF1PXA2MBU	Direct Replacement	PSF1PZA2MBU
PSF1PXA2MRD	Direct Replacement	PSF1PZA2MRD
PSF1PXA2MWH	Direct Replacement	PSF1PZA2MWH
PSF1PXA3.5MBL	Direct Replacement	PSF1PZC3.5MBL
PSF1PXA3.5MBU	Direct Replacement	PSF1PZC3.5MBU
PSF1PXA3.5MRD	Direct Replacement	PSF1PZC3.5MRD
PSF1PXA3.5MWH	Direct Replacement	PSF1PZC3.5MWH
PSF1PXA3MBL	Direct Replacement	PSF1PZA3MBL
PSF1PXA3MBU	Direct Replacement	PSF1PZA3MBU
PSF1PXA3MRD	Direct Replacement	PSF1PZA3MRD
PSF1PXA3MWH	Direct Replacement	PSF1PZA3MWH
PSF1PXD4.5MBL	No Replacement	
PSF1PXD4.5MBU	No Replacement	
PSF1PXD4.5MRD	No Replacement	
PSF1PXD4.5MWH	No Replacement	
PSF1PXD4MBL	Direct Replacement	PSF1PZC4MBL
PSF1PXD4MBU	Direct Replacement	PSF1PZC4MBU
PSF1PXD4MRD	Direct Replacement	PSF1PZC4MRD
PSF1PXD4MWH	Direct Replacement	PSF1PZC4MWH
PSF1PXD5.5MBL	No Replacement	
PSF1PXD5.5MBU	No Replacement	
PSF1PXD5.5MRD	No Replacement	
PSF1PXD5.5MWH	No Replacement	
PSF1PXD5MBL	Direct Replacement	PSF1PZC5MBL
PSF1PXD5MBU	Direct Replacement	PSF1PZC5MBU
PSF1PXD5MRD	Direct Replacement	PSF1PZC5MRD
PSF1PXD5MWH	Direct Replacement	PSF1PZC5MWH
PSF1PXD6.5MBL	No Replacement	
PSF1PXD6.5MWH	No Replacement	

