

**PCN725:** Carling RLD Dimmer Switch Stop Ship

**Issue Date:** December 12<sup>th</sup>, 2022

Dear Valued Customer,

This notice is to inform you of a product change affecting item(s) you have purchased from Littelfuse.

**Description of the Change:**

- We have temporarily stop shipping the attached list of dimmer switches due to supply chain interruptions of two board-level components (Microcontroller/MCU & EEPROM).

**Reason for The Change:**

- The current Microcontroller & EEPROM lead time have increased to 52 weeks from our supplier, preventing us from meeting production committments.
- We have identified replacements with lower operating temperature ranges (85 C vs previous component temperature range of 125 C) which results in lower output current capability and/or a lower operating temperature range due to internal temperature rise above component operating limits.

**Effective Date of the Change:**


- This stop-ship is effective immediately and until originally specified components are obtained.
- Additional testing, including maximum dimmer operating range, with the replacement components is in progress and we will provide detailed test results within the next 5 weeks.

**What You Need to Do:**

- If able, adjust request date for open orders on the attached parts to 12/1/23.
- If earlier fulfillment is required, finished goods utilizing identified deviations can be arranged on an order-by-order basis with your Customer Service or Inside Sales Representative.

If you have any questions, please contact your Customer Service or Inside Sales Representative. We appreciate your business and our continued partnership.

Sincerely,



Zachary Naughton  
Sr. Manager, Product Management  
Littelfuse Commercial Vehicle Products