

Subject: Hall Effect Sensors - COO Correction/Section 301 Tariff

Dear Valued Supplier,

November 13, 2018

This letter is to inform you of a Country of Origin correction and the Section 301 Tariff for our Hall Effect Sensors listed below. The Hall Effect Sensors were incorrectly called out on our Distribution Price book as COO "DE" when in fact they are manufactured in China. Effective immediately the below tariff charges will appear as a separate line item on our invoice for each line item affected, as well as on invoices for all open orders.

If you have any further questions, please reach out to Julie Dargie, Distribution Manager at jdargie@standexmeder.com.

PRODUCT SERIES	PRODUCT CATEGORY	MANUFACTURER PART NUMBER	***INTERNATIONAL HARMONIZE CODE	**ECCN NUMBER	*COUNTRY OF ORIGIN	Tariff Charge Per Piece
MH04	Hall Sensor	MH04-10S-300W	8536.41.0060	EAR99	CN	
MH04	Hall Sensor	MH04-11L-300W	8536.41.0060	EAR99	CN	
MH04	Hall Sensor	MH04-11S-300W	8536.41.0060	EAR99	CN	
MH21	Hall Sensor	MH21-10S-300W	8536.41.0060	EAR99	CN	
MH21	Hall Sensor	MH21-11L-300W	8536.41.0060	EAR99	CN	
MH21	Hall Sensor	MH21-11S-300W	8536.41.0060	EAR99	CN	

Thank you for your attention to this matter.

Julie Dargie

Senior Global Marketing & Distribution Manager